

MILLPWR^{G2}

PROGRAM TRAINING



HEIDENHAIN CORPORATION









333 East State Parkway, Schaumburg, IL 60173
1274 Hunt Road, Ashville, NY 14710

MILLPWRG2

Easy-to-Master Programming


Standardized menus make it easy to program common features like lines, arcs, custom pockets, hole patterns, and islands. To add a feature to your program, simply press a function key and then follow the prompts. MILLPWRG2 also includes an “engrave” option for engraving alphanumeric characters vertically, horizontally, diagonally or along an arc.



<p>TOOL</p> 	<p>RECT</p> 	<p>CIRCLE</p> 	<p>HOLES</p> 
<p>Program tools by diameter, length, type, direction, speed</p>	<p>Pocket, frame, face, slot</p>	<p>Pocket, frame, ring, helix</p>	<p>Full/partial circles, linear row/column, rectangular frame and array</p>
<p>POS</p> 	<p>LINE</p> 	<p>ARC</p> 	<p>BLEND</p> 
<p>Drill, bore, position</p>	<p>Defined by “from” and “to” points or by angles</p>	<p>Defined by “from” and “to” points or by sweep, center or 3-points</p>	<p>Insert a corner radius between two lines, two arcs or lines and arcs</p>

MILLPWR^{G2}

The Operating Console



1 12.1" Flat-Panel Color Display

2 Emergency "E" Stop

3 Soft Keys

4 Power On / Error Indicator Light

5 Potentiometer for Feed Rate Override

6 Go, Pause/Stop and Navigation/Move Table Arrow Keys


7 Axis Keys

8 Console Keypad

9 USB Port

MILLPWRG2

The Operating Console



- | | | | |
|--------------------------------|--------------------------------|---|---|
| 1 Power Switch | 5 Ethernet Port | 9 RS-232-C Connector | 12 KT 3D Grounding Edger Finder |
| 2 Power Connector | 6 USB Port | 10 Auxiliary Machine Interface (AMI) | 13 Encoder Inputs (W and Z axis) |
| 3 Servo Power Output | 7 KT 130 Edge Finder | 11 Servo connector (X, Y and Z) | |
| 4 Earth Ground Terminal | 8 Remote Stop/Go Switch | | |

Disengage Z Axis Feature


MILLPWR^{G2} provides the flexibility to switch between 2 axes and 3 axes operation within a single program and without changing setup parameters.

Disengaging the Z axis drive

1. Raise the quill, then loosen the quick release knob [1] on the front of the Z axis drive system.
2. Leave the Z BEGIN field blank when programming a step, or a one time milling operation.
3. When the operation is then performed, you will be prompted to manually position the quill when necessary.

Re-engaging the Z axis drive

1. Raise the quill handle to seat the ball nut into the nut block.
2. Tighten the quick release knob.
3. Lower the quill below the upper limit switch.





Find Home

Unlike many controls, MILL**PWRG2** does not require a move to a fixed machine home position. It instead establishes home using a distance encrypted reference pattern. This pattern allows the control to reestablish work piece zero, also called datum, from any location. During the homing process each axis will move about 1 to 2 inches. This is enough to learn the machine's current position.

- ▶ During start up, the Find Home soft key is provided.
- ▶ If the find home step is not performed at initial start up, it can be initiated at any time during operation. Press the Datum soft key, then press the Home soft key, and then press the Find Home soft key.
- ▶ A 3-axis system will move the table and quill. They will automatically move a few inches along the Z, Y, and then X to find home.
- ▶ A 2-axis system will move the table. The table will automatically move a few inches along the Y, and then X to find home. Then the control will prompt you to move the Z quill manually to home it.
- ▶ If a W-Axis scale is coupled with the Z, the control will then prompt you to move the W manually to find home.

Position-Trac™ will accurately re-establish work piece zero after a power loss, or shut down. When home has been found, the tool's position (relative to the most recent datum) will be displayed and soft limits reestablished.




The Digital Readout (DRO)

Soft key functions are shown in the lower display area (4) and change as needed as you use the control.

Pressing the key directly below the Soft keys label activates the described function.

The DRO mode allows the use of manual machining operations along with the milling function hard keys. The Move Table Feature allows you to move the table and quill at rapid or at a set feed rate to power feed


1. **Status Bar Display** for Servo Motor Status, Feed Rate, Tool, Datum, Scale, Skew, (Inch/MM), Estimated Time, Part Clock, Parts (run), Job Clock, and Time of Day
2. **Axes Display** (current position)
3. **Operator Intervention Message** line (OIM)
4. **Soft keys display area**
5. **Dialogue box display area** for milling functions



Available inactive soft key:
black key with white text

Unavailable soft key:
gray key with grey text

Active soft key:
blue key and green text



Status Bar Display

1. **Servo Motor Status**
On, Stop, Run, and Pause, indicates the servo motor status.
2. **Feed**
Rate indicates actual feed rate. Percentage indicated the percent of feed rate override adjustment from the feed rate override knob.
3. **Tool**
Indicates the current tool diameter and units. In PGM mode, indicates the programmed tool to be used for the highlighted step.
4. **Datum**
Indicates the current datum in use.
5. **Scale**
Indicates the amount of scaling factor being applied. 1.0000 equals no scaling.
6. **Skew**
Indicates the amount of skew angle being applied to the X, Y plane.
7. **Inch/MM**
Indicates current units in use. The current feed rate is displayed in these units per minute.
8. **Title of program**
9. **Line position / total lines**
10. **Estimated Time**
Indicates approximate run time for the current program at 100% feed rate override.
11. **Part Clock**
Times the cumulative running time of the current program. The timer is reset when a program is loaded.
12. **Parts**
(Run) shows the number of times the current program was run to create a part.
13. **Job Clock**
Shows total elapsed time for the current job (started and stopped by the operator).
14. **Time of Day**
Shows the current time.

Context Sensitive Help

When assistance is needed, the User Manual can be displayed. To use this help, in this example, the console is in PGM mode, and a Linear Engraving cycle is being programmed.

INFO

Using Context Sensitive Help

- ▶ Press the INFO key to open the on screen User Manual.
- ▶ A window will appear open to the section in the User Manual pertaining to the activity being performed.

Stop	Time: 0:03:14	Tool: 0.0638 Inch	Datum: 1	Scale: 1.0000	Skew: 0.0000°	Inch
EngraveSample.MPT 2 of 2 Engrave Line						
001	SET TOOL	Text				
002	ENGRAVE LINE	Engrave line sample				
Lower Left Corner						
	X	0.2500	Abs			
	Y	0.2500	Abs			
Character Height						
		0.7500				
Angle						
		0.0000				
Z						
	Begin	0.1000	Abs			
	End	-0.0200	Abs			
	Feed	10.0	IPM			

Context Sensitive Help: Use of the soft keys

1. The **Back** soft key navigates one page back in history per key press. History is not cleared when the Help Screen is exited.
2. The **Forward** soft key navigates one page forward in history per key press.
3. The **Previous Topic** soft key navigates one Topic up in the contents window per key press.
4. The **Next Topic** soft key navigates one Topic Down in the contents window per key press.
5. The **Contents View** soft key is a toggle key to show/ hide the contents view on the left hand side of the display.
6. To close, press the **Exit** soft key.

MILLPWR G2 User Manual
Milling and Drilling / Additional Milling Functions / Other steps

Engrave line

All ASCII characters within the decimal range of 32 - 126 are allowed, which includes Uppercase, Lowercase, Numbers, and Punctuation.

- ▶ From the **PGM** screen, press the **Program Steps** soft key.
- ▶ Then press the **Other Steps** soft key.
- ▶ In the popup menu select **Engrave Line**.
- ▶ With the cursor in the Text input field, press the **Alphanumeric Keyboard** soft key, and insert the desired text. The text entered can be edited using the **Up**, **Down**, **Left**, **Right** and **Backspace** soft keys. To insert a new line, use the **Insert Line** soft key.
- ▶ Enter the X and Y axes coordinates in the first page for the point at the lower left corner of the engraving, or in the second page for the center point of the engraving.
- ▶ Enter the character height.
- ▶ Enter the tilt angle if there is one.
- ▶ Enter the begin and end depths for the Z axis.
- ▶ Enter the Z axis feed rate.
- ▶ Select the font required from 3 choices, Simple, Stencil, or Stick, soft keys, or the drop down menu.
- ▶ Select the Modifier as either the Normal or Mirrored soft key. Normal is readable from left to right; Mirrored will make the engraving appear backwards.
- ▶ Enter the table's feed rate.
- ▶ Press the USE key.

Engrave Line configuration screen:

- Lower Left Corner: X, Y (Abs)
- Character Height
- Angle: 0.0000
- Z: Begin, End, Feed (Abs, IPM)

Soft keys: Back, Forward, Previous Topic, Next Topic, Contents View, Exit

NOTE: The **Previous Topic** and **Next Topic** soft keys will select the previous and next topic in the manual contents even if the **Contents View** is hidden.

Jog Modes



Pressing the MOVE TABLE soft key activates the jog mode. Jogs are performed at the currently active feed rate. Any time Jog mode is active, pressing the CLEAR key opens a window that allows you to set the feed rate. All axes can be moved simultaneously.



Continuous Moves

To Jog the machine using continuous movement, press the Move Table soft key. Make sure none of the incremental Jog keys are selected.


Press the appropriate ARROW key or a Move Z Soft Key to move in your desired direction. The machine will move at the current feed rate until the arrow key is released. The feed rate override knob can be used to control the feed rate.



Step Moves

Jog at one of the three predetermined step increments by pressing the appropriate soft key, then pressing an ARROW key or Move Z Soft Key to move in that direction. Each press of a direction key will initiate a move at the chosen increment. Press another step key to change the step distance or press the active step key to resume continuous jogging.

While the table is in motion, pressing the GO key will lock the feed and direction. This allow you hands free operation as the control feeds. Press the EXIT soft key to stop the control feed.



Job Setup

Parameters related to the job at hand are located in Job setup. These parameters are accessed from the DRO screen by pressing the SET-UP key.

SETUP

Scaling

This parameter allows you to adjust the finish size of a program by a scaling factor. The default is 1:1 or no scaling. A factor larger than one will grow the part size while a number less than one will shrink the part size. This is useful when creating a mold cavity for a material that shrinks to size after injection.

Feed Rate

- ▶ **Default** setting is the feed rate that will appear in a new program step. Choose a rate that you will use most of the time.
- ▶ **Dry Run** is the feed rate at which the machine will run when Dry Run is selected within Run Options.

Feed Rate Override

- ▶ **Max** is the maximum amount of override allowed when adjusted by the override knob.
- ▶ **Full Cut** percentage reduces the feed rate by this percentage when the tool is not able to stepover by the amount specified in a canned cycle.

Display

- ▶ **Peck:** This parameter changes the information requested for a peck between Number of cycles or Distance per peck.
- ▶ **Stepover:** Choose to display Percent of tool diameter, or distance per step.
- ▶ **Angles:** Choose Degrees Decimal or Degrees Minutes Seconds DMS. Use the decimal key to separate the degrees, minutes, and seconds. i.e. 47.22.12.
- ▶ **Res. Inch:** Choose the DRO Display resolution, 0.0001, 0.0005, or 0.0010.
- ▶ **Res MM:** Select Display resolution, 0.001, 0.005, or 0.010.
- ▶ **Manual Z:** Select Switch to Incremental, or Do Nothing. Incremental switches the DRO to show the incremental distance to the end of each move. Do nothing keeps the display at the current selected value of either Abs or INCR.
- ▶ **Help Images:** Automatic or On changes the graphic help screen display when programming.

Job Setup	
Scaling	Scaling <input type="text" value="1.0000"/>
Feed Rate	Default <input type="text" value="10.0"/> Inch
	Dry Run <input type="text" value="80.0"/>
Feed Rate Override	Full Cut <input type="text" value="100"/> %
	Max <input type="text" value="150%"/>
Display	Peck/Pass <input type="text" value="Number of Cycles"/>
	Stepover <input type="text" value="Percentage"/>
	Angles <input type="text" value="Degrees"/>
	Res. Inch <input type="text" value="0.0001"/>
	Res. MM <input type="text" value="0.001"/>
	Manual Z <input type="text" value="Use Inc"/>
	Help Imgs <input type="text" value="On"/>
Job Clock - Parts Counter	Parts <input type="text"/>

Job Setup

Parameters related to the job at hand are located in Job setup. These parameters are accessed from the DRO screen by pressing the SETUP key.



Job Clock – Parts Counter

The job clock controls are accessed when this field is highlighted. Enter the starting number for the parts to be counted and adjust the number as needed during a run.



Job Clock and Parts Counter Keys

Probing Radius

Enter the radius of your electronic touch probe here. The radius will be adjusted for when probing cycles are used.

Job Setup	
Scaling	
Scaling	<input type="text" value="1.0000"/>
Feed Rate	
Default	<input type="text" value="10.0"/> Inch
Dry Run	<input type="text" value="80.0"/>
Feed Rate Override	
Full Cut	<input type="text" value="100"/> %
Max	<input type="text" value="150%"/>
Display	
Peck/Pass	<input type="text" value="Number of Cycles"/>
Stepover	<input type="text" value="Percentage"/>
Angles	<input type="text" value="Degrees"/>
Res. Inch	<input type="text" value="0.0001"/>
Res. MM	<input type="text" value="0.001"/>
Manual Z	<input type="text" value="Use Inc"/>
Help Imgs	<input type="text" value="On"/>
Job Clock - Parts Counter	
Parts	<input type="text"/>

Job Setup	
Probing	
Radius	<input type="text" value="0.098425"/>

Install Setup

Parameters that effect machine performance are listed under Install Setup. These parameters are password protected to prevent unintentional modification. They are accessed from the DRO screen by pressing the SETUP key then the Install Setup soft key.



SETUP

Install
Setup

Operator password: 8891

Settings


- ▶ **X Y Z W Encoder:** These parameters are used for establishing the encoder resolution and count direction. If changed, the control can become unpredictable.
- ▶ **Table limits:** These parameters establish machine travel limits once home is established.
- ▶ **Z Axis Control:** Use this to disable and enable the Z-Axis. When disabled, the control is restricted to two axis operation.
- ▶ **Max Servo Speed:** Set the maximum servo speed of the control with this parameter. Tuning is effected with by this parameter and resetting to 100 ipm before tuning is recommended if changed.
- ▶ **Machine Functions:** Provides access to coolant and spindle function keys when the optional Auxiliary Machine Interface (AMI) is installed. Some spindle functionality requires an electronic variable speed spindle. Four additional outputs are available as well. Your current software version can be found here.



Install Setup

Tools

- ▶ **Compensation:** Adjust for minor linear error discrepancies between machine and control or enter a non-linear error compensation table determined by laser calibration.
- ▶ **OSC:** This is the oscilloscope where servo tuning via the analog wizard and machine accuracy can be measured.
- ▶ **System Information:** Lists hardware, features, and your serial number.
- ▶ **Date / Time:** Sets the local time and date.
- ▶ **Network:** Provides settings necessary to join to a data network.
- ▶ **Shares:** Sets up sharing within the network.
- ▶ **Screensaver:** Access to the system screen saver features.



Install Setup

Diagnostics

- ▶ **System Monitor:** Machine position and motor status and reference mark verification. AMI inputs and outputs, spindle speed input, e-stop status, probe status, and pendant status.




System monitor features

System Monitor	
X Axis	Abs <input type="text" value="0.0000"/>
	Ref Mark <input type="text"/>
	Status <input type="text" value="Off"/>
Y Axis	Abs <input type="text" value="0.0000"/>
	Ref Mark <input type="text"/>
	Status <input type="text" value="Off"/>
Z Axis	Abs <input type="text" value="0.0000"/>
	Ref Mark <input type="text"/>
	Status <input type="text" value="Off"/>
W Axis	Status <input type="text" value="Not Present"/>

System Monitor	
AMI Inputs	
Spindle Fault (I7)	<input type="text" value="Off"/>
Guard Open (I22)	<input type="text" value="Off"/>
Remote GO (I25)	<input type="text" value="Off"/>
Low Oil (I26)	<input type="text" value="Off"/>
Spindle Gear (I27)	<input type="text" value="Off"/>
At Speed (I23)	<input type="text" value="Off"/>
At Rest (I24)	<input type="text" value="Off"/>
AMI Outputs	
Spindle FWD (O4)	<input type="text" value="Off"/>
Spindle REV (O5)	<input type="text" value="Off"/>
Coolant Flood (O3)	<input type="text" value="Off"/>
Coolant Mist (O18)	<input type="text" value="Off"/>
Lube/Oil (O8)	<input type="text" value="Off"/>
Aux 1 (O19)	<input type="text" value="Off"/>
Aux 2 (O27)	<input type="text" value="Off"/>
Aux 3 (O28)	<input type="text" value="Off"/>
Aux 4 (O29)	<input type="text" value="Off"/>

System Monitor	
Spindle	
Speed Inputs	<input type="text" value="Not Active"/>
DAC Voltage	<input type="text" value="0.00 VDC"/>
Circuit Test	
E-Stop Status	<input type="text" value="Closed"/>
Z Limit Status	<input type="text" value="Closed"/>
Peripherals	
Probe	<input type="text" value="Not Active"/>
Pendant	<input type="text" value="Not Active"/>

- ▶ **Keypad Test:** Test key functionality, press, release, and function.
- ▶ **Disk Utilization:** Used vs Free space, number of folders and files.
- ▶ **System Statistics:** Time on, Time servos active, Distances traveled.
- ▶ **Remote Diagnostics:** Allows a field service technician remote access to a control.




Axis Conventions

Count Direction

Machine movement is described with positive and negative numbers. Standard milling conventions use positive and negative count directions for the X, Y and Z-axis described by the following:

- ▶ **X axis:** The table moves to the left (tool moves to the right) for a positive count direction.
- ▶ **Y axis:** The table moves toward you (tool moves away from you) for a positive count direction.
- ▶ **Z axis:** The quill moves up from the table surface for a positive count direction.




Cartesian Coordinates

A cartesian coordinate is a position described with X by Y values.


Polar Coordinates

A polar coordinate is a position described with an angle by radius. When you are dealing with angles, polar input may simplify programming.

Reference Point		
Point		
X	<input type="text" value="5.0000"/>	Abs
Y	<input type="text" value="4.0000"/>	Abs
Z		
End	<input type="text" value="0.0000"/>	Abs



Reference Point		
Point		
R	<input type="text" value="6.4031"/>	Abs
A	<input type="text" value="38.6598"/>	Abs
Z		
End	<input type="text" value="0.0000"/>	Abs



Absolute & Incremental Work Piece Positioning


Absolute Work Piece Positions

Absolute coordinates are position coordinates that are referenced to a datum also known as work piece zero.

Absolute positions always refer to datum.

Example 1: Holes dimensioned in absolute coordinates

Hole 1	Hole 2	Hole 3
X = 10 mm	X = 30 mm	X = 50 mm
Y = 10 mm	Y = 20 mm	Y = 30 mm




Example 1

Incremental Work Piece Positions

Incremental coordinates typically reference current location but can also reference a previous step within the program.

Example 2: Holes dimensioned in incremental coordinates

Hole 4 (Absolute)	Hole 5 Inc from 4	Hole 6 Inc from 5
X = 10 mm	X = 20 mm	X = 20 mm
Y = 10 mm	Y = 10 mm	Y = 10 mm



Example 2

Teach Positions

With the exception of Datum, whenever an X, Y, or Z coordinate is being entered, the Teach Position soft key will appear. When pressed, the current absolute position of the spindle is inserted in the active axis field. This allows you to transfer existing feature locations into a program step. Use the keypad to adjust the taught position in order to compensate for the tool tip use to locate the feature and to adjust as otherwise required.

Teach
Position

DRO Position Preset

To access the PRESET function, when in the DRO:

- ▶ Press the ABS/INCR key on the front panel to switch to the incremental mode.
- ▶ Press the Preset soft key or one of the axis keys to open the PRESET dialogue.
- ▶ Enter an X, Y, and or Z absolute value. The distance to this location will be preset in the incremental display. Manually move the machine to incremental zero to achieve this position.
- ▶ Press the CANCEL key at any time to cancel and exit the PRESET dialogue.

The screenshot shows the DRO Position Preset interface. At the top, status information includes: Stop, Feed: 0.0 100%, Tool: 0.5000 Inch, Datum: 1, Scale: 1.0000, Skew: 0.0000°, and Inch. Below this, a 'Presets' dialog box is open, showing input fields for X (1.0000), Y (0.1875), and Z (-0.1000), all labeled 'Abs'. A red arrow points from the text 'Target Position entered as absolute values' to the X input field. The main display area shows four axes: X (-1.5000 INC), Y (-1.8750 INC), Z (1.1000 INC), and S (0 OFF). Each axis has an analog slider and a digital display. A red arrow points from the text 'Analog sliders indicate distance to go' to the X slider, and another red arrow points from the text 'Digital Display indicates distance to go target positions' to the X digital display. At the bottom, there are soft keys for Zero X, Zero Y, and Zero Z.

Soft keys are available to zero the incremental display for quick “zero and go” operations.



Establishing a Datum


Where you locate your datum will vary from job to job. Choose a location that best suits the job at hand. Placing it where the majority of your dimensions refer, will speed up programming and reduce errors. There may be a specified datum or multiple datum on a print. MILLPWRG2 allows you to set up to 99 datum locations. Insert an edge finder, indicator, or tool, into the spindle. Choose the device that best suits your needs. i.e. an indicator is best for locating a center point.

To establish Datum at a corner of your work-piece:

- ▶ From the DRO mode insure you are in absolute and press the Datum soft key.
- ▶ Enter a datum number from 1 to 99 as the datum to be defined.
- ▶ To locate an edge as illustrated to the right, move your tool or edge finder until it touches the work piece.
- ▶ Press the appropriate soft key to zero the axis you are setting, then raise the quill and move to center the tool on the edge or instead add or subtract the radius of the tool being used plus any stock allowance. If the datum is several inches further in the part you can enter this distance as well. Once entered, this location is set and you can maneuver to the other axis and repeat this process.
- ▶ When both the X and Y are located, place the tool you wish to use in the spindle and touch the top of the work piece.
- ▶ Press Zero Z to set the datum at the top of your work piece or enter the distance to the desired datum in the Z field.


Set Datum		Estimated Time	Part Clock	Parts	Job Clock	Time of Day
Datum Number	1	0:03:14	0:00:00	0	1:37	5:49 pm
Datum		INC 0.0000		3.4499	ABS	X
X	3.4499	INC 0.0000		5.5711	ABS	Y
Y	5.5711	INC 0.0000		5.0000	ABS	Z
Z	5.0000	INC 0.0000		0	OFF	S
Retract	Z	OVR 100%				
Skew						
Angle	0.0000					
Points	0					

Zero X Zero Y Zero Z Probe Adjust Home Move Table




Skew

- ▶ The skew function compensates for the angle of your work piece when it is not parallel with either the X or Y axis.
- ▶ To compensate for the skewed part, touch off on two or more points along one axis, either X or Y.
- ▶ Use an electronic edge finder to enter points with each touch. With a mechanical edge finder or indicator, locate the edge and press the Teach Position soft key to enter points.
- ▶ Skewing adjusts the edge you choose making it parallel with the nearest axis of travel. Do not use points along a curve, along two different lines, or on a 45 degree angle.
- ▶ With rough surface, enter multiple points to more accurately calculate the skew angle. Locating points that are farther apart is also more accurate than points that are near each other.
- ▶ The skew feature does not work with G-code programs. Remove any skew angle prior to running a G-code program.



Retract

The retract is a plane above datum zero from where the tool begins a cycle and then returns to upon completion. All rapid movement between cycles occurs at this plane. By setting a retract position, you can ensure that the tool is clear when moving from one position to the next. Enter a Z axis retract position sufficient to clear the work piece and fixturing or press the CLEAR key to clear any value. With no value, the quill will revert to the upper travel limit between steps.






Example: Setting Datum at the Top Front Left Corner

Datum

- ▶ Lower the tool then hand crank the table along the X axis, slowly spinning the tool by hand as you go (Place the spindle in neutral for this). Stop when the tool contacts the part.
- ▶ Using the keypad, enter into the X field the location of the spindle center from the edge (tool radius). In the illustration to the right, the value would be negative because the tool's center is on the negative side of the edge.
- ▶ Press ENTER or the down arrow to move to the next field. Position the tool in front and move the Y axis, slowly spinning the tool by hand as you go until the tool contacts the part.
- ▶ Using the keypad, enter into the Y field the location of the spindle center from the edge (tool radius). In the illustration to the right, the value would be negative because the tool's center is on the negative side of the edge.
- ▶ Press the ENTER or the down arrow to move to the next field. Position the tool so that its tip touches the top surface of the part.
- ▶ Press the Z = 0 soft key or enter a zero in the Z axis field.
- ▶ Press ENTER. With the data entered, the cursor will highlight the next field.

Retract

The retract is a plane above datum zero from where the tool begins a cycle and then returns to upon completion. All rapid movement between cycles occurs at this plane. By setting a retract position, you can ensure that the tool is clear when moving from one position to the next. Enter a Z axis retract position sufficient to clear the work piece and fixturing or press the CLEAR key to clear any value. With no value, the quill will revert to the upper travel limit between steps.



Using the Probing Cycles

When in the Datum field, three probing cycles are available to assist you.

- ▶ Press the Probe soft key to access three probing cycles: Edge, Centerline and Circle Center.
- ▶ Press the Use Tool soft key if you are not using a KT130 or KT3D touch probe.
- ▶ Press the Edge, Centerline, or Circle Center soft key to select the operation you wish to use.
- ▶ Move to the edge of your work piece. If using a touch probe, contact with the part will trigger the entry or if using a mechanical edge finder press the Teach

soft key when the indicator triggers.

Edge


Sets the datum with a single trigger of the edge finder. The system will prompt to "Move to edge." Start movement until the edge finder is triggered. Once triggered, the system will exit the probing mode and set datum for the moving axis. The probe tip compensation is automatically adjusted by the value entered in the job setup parameter. This also works when using a probe while in the regular datum entry field.

Centerline

Sets the datum with 2 triggers of the edge finder, bisecting the distance between the two points. The axis that is used for the first trigger must also be used for the second. Centerline works for only one axis of travel at a time.

Circle Center


Sets the datum using 3 points of a circle. This operation functions in the X - Y axis by touching three points along a circle or radius. Both X and Y will be established with this operation. The farther apart your three points are, the more accurate the center point will be.



MILLPWRG2

Single-Step Milling Functions

Single-Step Milling Functions can be run as stand alone operations. With the exception of the blend key, each of these keys offer at least one single-step cycle.



Set Tool

From the DRO, press the tool key to open the tool dialog window. Enter the tool information then press Use or GO to initiate the tool change. When completed the current tool data will update to indicate the new tool being used. In a program press Use to save the tool step in a program.

Tool Number

Enter a number to select a pre-established tool from the tool library. Do not use a number if defining the tool within the step.

Diameter

Used when left or right offset is used. Diameter is the only mandatory information required.

Length

An offset used to offset the tool relative to Z datum.

Plunge / Ramp Angle

Sets the angle the tool enters the cut.

Tool Type

Helps you differentiate tools with similar diameters.

Spindle

Direction and speed can be entered and you will be prompted to set these at run time or G2 will be activate the spindle if equipped to do so.

Tool Position

A location the machine will move to prior to pausing for the change. Enter one or more axis value as needed.

Require Change


- ▶ When set to “yes” will force the tool change even when the current tool matches the new tool.
- ▶ When set to “no,” the tool change is skipped when the tool matches.



Set Tool	
Tool Number	<input type="text"/>
Size	
Diameter	<input type="text" value="0.5000"/> Inch
Length	<input type="text"/>
Plunge / Ramp	
Angle	<input type="text"/>
Tool Type	<input type="text" value="Flat End Mill"/>
Spindle	<input type="text" value="Off"/>
Speed	<input type="text"/> RPM
Tool Position	
X To	<input type="text"/> Abs
Y To	<input type="text"/> Abs
Z To	<input type="text"/> Abs
Require Change	<input type="text" value="No"/>

Tool Library

From the DRO, press the tool key to open the tool dialog window then press the Tool Table soft key to enter the tool library. Arrow down to the tool number you wish to edit and press ENTER.



Tool Number

Use the arrow keys to highlight the tool number you wish to add or edit.

Diameter

Used when left or right offset is used. This is the only mandatory information required.

Length

An incremental adjustment used to offset the tool relative to Z datum. After insuring no offset is active, touch a tool to datum zero and press the Teach soft key to calibrate.


Type

Helps you differentiate tools with similar diameters. Press enter and use the arrow keys to select.

Plunge Angle

The angle of entry a tool will use when feeding to programmed depth.
 $0^\circ = 90^\circ$.

Tool	Diameter	Length	Type	Plunge Angle
1	0.25	0	Flat End Mill	5
2	0.3126	0	Flat End Mill	15
3	0.5	0	Flat End Mill	90
4	0.75	0	Roughing Mill	25
5	0.125	0	Pilot Drill	0
6	0.25	0	Pilot Drill	0
7	0.25	0	Drill	0
8	0.4126	0	Drill	0
9	6	0	Fly Cutter	0
10	0.5	0	Special Mill	30
11	0	0		30
12	0	0		30



Position / Drill

The POS key opens the POSITION / DRILL dialogue. The Position / Drill function will move the table to specific position and execute a drilling, boring, or positing (2-Axis drilling) operation.



Point

Enter the X and Y position to locate the single drill operation.

Z

- ▶ **Begin** is where the tool will rapid to. From there it will **Feed** at the given rate to the End value. Feed The given rate to the
- ▶ **Peck** will lift the tool by 0.01" at every peck you define by number or distance. With the Drill option selected, the tool will feed down and rapid up. With bore selected, the tool will feed in both directions. With position selected the operation reverts to a two axis operation pausing at each location until GO is pressed, useful for manually tapping.

Tool Retract

Causes the tool to lift to the Z begin. When retracted, the tool will dwell for the number of seconds entered to allow the tool and work piece to cool down if needed.

Tool

Cannot be changed here but shows the tool information of the last tool step programmed to insure you the correct tool will be used.

Dwell

The number of seconds the tool will dwell at the bottom of the cycle and is useful to insure the bottom is finished and smooth.

Position / Drill		
Point	X	Abs
	Y	Abs
Z	Begin	Abs
	End	Abs
	Peck	Number
	Drill	
	Feed	IPM
Tool Retract		Number
	Dwell	Sec
Tool	0.2500	Inch
		Type
Tool		
	Dwell	Sec

Mill Line

The LINE key opens the line dialogue box allowing you to define a line from beginning to end. This step is capable of running as a stand alone operation in both DRO and PGM mode and can also be also be part of a continuous path in PGM mode when programming a continuous path. The begin point, Z information, offset and feeds are carried forward in PGM mode so you do not need to enter redundant information. These can be changed if needed.

From

X1 Y1 Define the start point of the line. These can be cartesian or polar, absolute (ABS) or incremental (INC) from an external reference point.

To

X2 Y2 The end of the line and can be cartesian or polar, absolute (ABS) or incremental (INC) from the begin point or an external reference point.

Z

- ▶ **Begin** is where the tool will rapid to. From there it will feed at the given rate to the End value at the **Feed** provided.
- ▶ This feed is for the Z axis only. The feed below is for the X, Y plane.
- ▶ The tool will then proceed to the “To” point. It then rapids up to the retract plane set in datum.
- ▶ If the line is part of a continuous tool path the tool will not lift at the end but continue along the established path.
- ▶ Changing the “End” will break up a continuous path.


Angle

Allows you to create a line by programming to an X or a Y point at this given angle. i.e. from X0, Y0, to X2 at 20 degrees.

Tool

Cannot be changed here but shows the tool information of the last tool step programmed to remind you of which will be used.

- ▶ **Offset:** Allows you to specify left, right, or center. Changing the offset will breakup a continuous path.
- ▶ **Feed:** Establishes the rate at which the tool will feed along the X, Y plane. This can be changed without breaking a continuous path.



Mill Line		
From		
X1	<input type="text"/>	Abs
Y1	<input type="text"/>	Abs
To		
X2	<input type="text"/>	Abs
Y2	<input type="text"/>	Abs
Z		
Begin	<input type="text" value="0.1000"/>	Abs
End	<input type="text" value="-0.0200"/>	Abs
Feed	<input type="text" value="10.0"/>	IPM
Angle		
	<input type="text"/>	
Tool		
	<input type="text" value="0.2500"/>	Inch
	<input type="text"/>	Type
Offset	Center	▼
Feed	<input type="text" value="10.0"/>	IPM

Mill Arc

The ARC key opens the arc dialogue allowing you to define an arc with both beginning and end. This step is capable of running as a stand alone operation in both DRO and PGM mode and can also be part of a continuous path in a program. When used in a continuous path, the begin point, Z Information, offset and feeds are carried forward so you do not need to enter redundant information. These can be changed if needed.

From

X1 Y1 define the start point of the arc. These can be cartesian or polar, absolute (ABS) or incremental (INC) from an external reference point.

To

X2 Y2 is the end of the arc and can be cartesian or polar, absolute (ABS) or incremental (INC) from the begin point or an external reference point.

Z

- ▶ **Begin** is where the tool will rapid to. From there it will feed at the given rate to the **End** value at the Feed provided.
- ▶ This feed is for the Z axis only. The feed below is for the X, Y plane.
- ▶ The tool will then proceed to the “To” point. It then rapids up to the retract plane set in datum.
- ▶ If the line is part of a continuous tool path the tool will not lift at the end but continue along the established path.
- ▶ Changing the “End” will break up a continuous path.




Mill Arc			
From	X1 <input type="text"/>	Abs	Tool
	Y1 <input type="text"/>	Abs	
To	X2 <input type="text"/>	Abs	<input type="text" value="0.2500"/> Inch
	Y2 <input type="text"/>	Abs	<input type="text"/> Type
Z	Begin <input type="text" value="0.1000"/>	Abs	Offset <input type="text" value="Center"/>
	End <input type="text" value="-0.0200"/>	Abs	Feed <input type="text" value="10.0"/> IPM
	Feed <input type="text" value="10.0"/>	IPM	Center
Radius	<input type="text"/>	Minor	X <input type="text"/>
Direction	<input type="text" value="CCW"/>		Y <input type="text"/>
			3rd Point
			X3 <input type="text"/>
			Y3 <input type="text"/>
			Sweep Angle
			<input type="text"/>

Mill Arc

Radius

Establishes the size of the arc. Minor or Major can be established. Minor arcs are less than 180 degrees while Major arcs are greater than 180 degrees.



From		Tool	
X1	<input type="text"/>	<input type="text" value="0.2500"/>	Inch
Y1	<input type="text"/>	<input type="text"/>	Type
To		Offset	Center
X2	<input type="text"/>	Feed	<input type="text" value="10.0"/>
Y2	<input type="text"/>	Center	
Z		X	<input type="text"/>
Begin	<input type="text" value="0.1000"/>	Y	<input type="text"/>
End	<input type="text" value="-0.0200"/>	3rd Point	
Feed	<input type="text" value="10.0"/>	X3	<input type="text"/>
Radius		Y3	<input type="text"/>
<input type="text"/>		Sweep Angle	
Direction		<input type="text"/>	
<input type="text"/>		CCW	

Direction

Establishes clockwise (CW) or counter clockwise (CCW) direction.

Tool

- ▶ Cannot be changed here but shows the tool information of the last tool step programmed to remind you of which will be used.
- ▶ **Offset:** Allows you to specify left, right, or center. Changing the offset will breakup a continuous path.
- ▶ **Feed:** Establishes the rate at which the tool will feed along the X, Y plane. This can be changed without breaking a continuous path.

Mill Arc

Center

Allows you to define the center point of an arc. This is useful if a radius is not defined on your print. Do not enter a radius prior to entering the center point.

3rd Point


Provides you with another method of defining an arc. By programming a "From," "To" and "3rd Point," an arc can be determined. The "3rd Point" does not have to be within the "From" and "To" points.

Sweep Angle

An alternative entry for when the "From" or "To" point is unknown. If a "From" point is entered with a radius and a sweep angle, the "To" point can be calculated.



Mill Arc			
From	X1 <input type="text"/>	Abs	Tool
	Y1 <input type="text"/>	Abs	
To	X2 <input type="text"/>	Abs	<input type="text" value="0.2500"/> Inch
	Y2 <input type="text"/>	Abs	<input type="text"/> Type
Z	Begin <input type="text" value="0.1000"/>	Abs	Offset <input type="text" value="Center"/>
	End <input type="text" value="-0.0200"/>	Abs	Feed <input type="text" value="10.0"/>
	Feed <input type="text" value="10.0"/>	IPM	Center
Radius	<input type="text"/>	Minor	X <input type="text"/>
Direction	<input type="text" value="CCW"/>		Y <input type="text"/>
			3rd Point
			X3 <input type="text"/>
			Y3 <input type="text"/>
			Sweep Angle
			<input type="text"/>




Circle Pocket

The CIRCLE key activates a pop up list of circle features. Highlight the Pocket option and press ENTER or press 7 on the keypad to select Pocket. Circle pocket allows you to define a complete stand alone circular pocket. This step is capable of running in both DRO and PGM mode.

Center

X Y define the center point of the circle. This can be cartesian or polar absolute (ABS) values relative to Datum Zero.



Z


- ▶ Begin is where the tool will rapid to. From there it will feed at the given rate to the End value at the Feed provided.
- ▶ This feed is for the Z axis only.
- ▶ Pass will divide the operation by the number of times or by the distance you program providing multiple passes to final depth.

Radius

Establishes the size of the pocket.

Direction

Establishes clockwise (CW) or counter clockwise (CCW) direction.



Circle			
Center		Finish	
X	<input type="text"/>	Abs	Bottom <input type="text" value="0.0000"/>
Y	<input type="text"/>	Abs	Side <input type="text" value="0.0000"/>
Z		Feed <input type="text" value="0.0"/>	IPM
Begin	<input type="text" value="0.1000"/>	Abs	Direction <input type="text" value="CCW"/>
End	<input type="text" value="-0.0200"/>	Abs	Stepover
Pass	<input type="text"/>	Number	
Feed	<input type="text" value="10.0"/>	IPM	Type
Radius	<input type="text"/>		<input type="text" value="Pocket"/>
Direction	<input type="text" value="CCW"/>		

Circle Pocket

Tool

Cannot be changed here but shows the tool information of the last tool step programmed to remind you of the tool that will be used.

Feed

Establishes the rate at which the tool will feed along the X, Y plane.

Finish


- ▶ **Bottom** amount of stock to leave for the final finish pass
- ▶ **Side** amount of stock to leave for the final finish pass
- ▶ **Feed rate** and **Direction** to use

Stepover

Allows you to define the percentage of the tool to use per pass for the roughing cut. The default is 50%.

Type

Allows you to choose contour if you wish to use the shape to define an Island within a custom pocket.



Circle			
Center		Finish	
X	<input type="text"/>	Abs	Bottom <input type="text" value="0.0000"/>
Y	<input type="text"/>	Abs	Side <input type="text" value="0.0000"/>
Z		Feed <input type="text" value="0.0"/>	IPM
Begin	<input type="text" value="0.1000"/>	Abs	Direction <input type="text" value="CCW"/>
End	<input type="text" value="-0.0200"/>	Abs	Stepover
Pass	<input type="text"/>	Number	
Feed	<input type="text" value="10.0"/>	IPM	Type
Radius	<input type="text"/>		
Direction			
		<input type="text" value="CCW"/>	
Tool			
	<input type="text" value="0.2500"/>	Inch	
	<input type="text"/>	Type	
Feed	<input type="text" value="10.0"/>	IPM	

Circle Frame

The CIRCLE key activates a pop up list of circle features. Highlight the Frame option and press ENTER or press 8 on the keypad to select Frame. Circle frame allows you to define a complete stand alone circular frame. This step is capable of running in both DRO and PGM mode.

Center

X Y define the center point of the circle. This can be cartesian or polar, absolute (ABS) or incremental (INC) from an external reference point.

Z



- ▶ **Begin** is where the tool will rapid to. From there it will feed at the given rate to the **End** value at the **Feed** provided.
- ▶ This feed is for the Z axis only.
- ▶ **Pass** will divide the operation by the number of times or by the distance you program providing multiple passes to final depth.

Radius

Establishes the size of the arc. Minor or major can be established.


Direction

Establishes clockwise (CW) or counter clockwise (CCW) direction.



Circle Frame			
Center	X	<input type="text"/>	Abs
	Y	<input type="text"/>	Abs
Z	Begin	<input type="text" value="0.1000"/>	Abs
	End	<input type="text" value="-0.0200"/>	Abs
	Pass	<input type="text"/>	Number
	Feed	<input type="text" value="10.0"/>	IPM
Radius		<input type="text"/>	
Direction		<input type="text" value="CCW"/>	
Tool		<input type="text" value="0.2500"/>	Inch
		<input type="text"/>	Type
Offset		<input type="text" value="Center"/>	
Feed		<input type="text" value="10.0"/>	IPM
Finish		<input type="text"/>	Cut
	Feed	<input type="text" value="0.0"/>	IPM
	Direction	<input type="text" value="CCW"/>	

Circle Frame



Tool

- ▶ Cannot be changed here but shows the tool information of the last tool step programmed to insure you the correct tool will be used.
- ▶ **Offset:** Allows you to specify left, right, center, inside, or outside.
- ▶ **Feed:** Establishes the rate at which the tool will feed along the X, Y plane.

Finish

- ▶ **Cut:** Establishes the amount of stock to leave for the final finish pass
- ▶ **Feed rate** and **Direction** to use

Circle Frame			
Center	X	<input type="text"/>	Abs
	Y	<input type="text"/>	Abs
Z	Begin	<input type="text" value="0.1000"/>	Abs
	End	<input type="text" value="-0.0200"/>	Abs
	Pass	<input type="text"/>	Number
	Feed	<input type="text" value="10.0"/>	IPM
Radius		<input type="text"/>	
Direction		<input type="text" value="CCW"/>	
Tool		<input type="text" value="0.2500"/>	Inch
		<input type="text"/>	Type
Offset		<input type="text" value="Center"/>	
Feed		<input type="text" value="10.0"/>	IPM
Finish		<input type="text"/>	Cut
	Feed	<input type="text" value="0.0"/>	IPM
	Direction	<input type="text" value="CCW"/>	

Circle Ring

The CIRCLE key activates a pop up list of circle features. Highlight the Ring option and press ENTER or press 9 on the keypad to select ring. Circle ring allows you to define a complete stand alone circular ring. This step is capable of running in both DRO and PGM mode.

Center

X Y define the center point of the circle. This can be cartesian or polar, absolute (ABS) or incremental (INC) from an external reference point.

Z



- ▶ **Begin** is where the tool will rapid to. From there it will feed at the given **Feed** rate to the **End** value.
- ▶ This feed is for the Z axis only.
- ▶ **Pass** will divide the operation by the number of times or by the distance you program providing multiple passes to final depth.

Radius

- ▶ Establishes the size of the ring.
- ▶ **Outside** establishes the outer radius.
- ▶ **Inside** establishes the inner radius.

Direction

Establishes clockwise (CW) or counter clockwise (CCW) direction.



Ring			
Center		Finish	
X	<input type="text"/>	Abs	Bottom <input type="text" value="0.0000"/>
Y	<input type="text"/>	Abs	Side <input type="text" value="0.0000"/>
Z		Feed <input type="text" value="0.0"/>	IPM
Begin	<input type="text" value="0.1000"/>	Abs	Direction <input type="text" value="CCW"/>
End	<input type="text" value="-0.0200"/>	Abs	Stepover
Pass	<input type="text"/>	Number	
Feed	<input type="text" value="10.0"/>	IPM	Type
Radius		<input type="text" value="Pocket"/>	
<input type="text"/>		Outside	
<input type="text"/>		Inside	
Direction			
<input type="text" value="CCW"/>			
Tool			
<input type="text" value="0.2500"/>		Inch	
<input type="text"/>		Type	
Feed	<input type="text" value="10.0"/>	IPM	

Circle Ring

Tool

Cannot be changed here but shows the tool information of the last tool step programmed to insure you the correct tool will be used.

Feed

Establishes the rate at which the tool will feed along the X, Y plane.

Finish


Establishes the amount of stock (Cut) to leave for the final finish pass along with the Feed rate and Direction to use.

Stepover

Allows you to define the percentage of the tool to use per pass for the roughing cut. The default is 50%.

Type


Allows you to choose contour if you wish to use the shape to define an Island within a custom pocket.



Ring			
Center		Finish	
X	<input type="text"/>	Abs	Bottom <input type="text" value="0.0000"/>
Y	<input type="text"/>	Abs	Side <input type="text" value="0.0000"/>
Z		Feed <input type="text" value="0.0"/>	IPM
Begin	<input type="text" value="0.1000"/>	Abs	Direction <input type="text" value="CCW"/>
End	<input type="text" value="-0.0200"/>	Abs	Stepover
Pass	<input type="text"/>	Number	<input type="text" value="50"/> %
Feed	<input type="text" value="10.0"/>	IPM	Type
Radius		<input type="text" value="Pocket"/>	
<input type="text"/>		Outside	
<input type="text"/>		Inside	
Direction		<input type="text" value="CCW"/>	
Tool			
	<input type="text" value="0.2500"/>	Inch	
	<input type="text"/>	Type	
Feed	<input type="text" value="10.0"/>	IPM	

Helix

The CIRCLE key activates a pop up list of circle features. Highlight the Helix option and press ENTER or press 4 on the keypad to select Helix. Helix allows you to define a complete stand alone Helix. This step is capable of running in both DRO and PGM mode. Helix allows you to mill threads both inside and outside, left and right handed.



Center

X Y define the center point of the circle. This can be cartesian or polar, absolute (ABS) or incremental (INC) from an external reference point.

Z


- ▶ **Begin:** Where the tool will rapid to.
- ▶ **End:** Feeds along the given pitch to the end value provided then rapids up to the retract plane as set in datum.

Radius

Establishes the size of the Helix.

Direction

Establishes clockwise (CW) for right handed or counter clockwise (CCW) for left handed direction.



Helix		
Center	X	Abs
	Y	Abs
Z	Begin	0.1000 Abs
	End	-0.5200 Abs
Radius		
Direction	CW	
Revolutions		Rev/in
		Revs
Tool		0.2500 Inch
		Type
	Offset	Inside
Feed	10.0	IPM

Helix

Revolutions


- ▶ **Rev / in** (revolution per inch) establishes a thread pitch
- ▶ **Revs** (total number of revolutions) if you are simply clearing a hole.

Tool

- ▶ Cannot be changed here but shows the tool information of the last tool step programmed to insure you the correct tool will be used.
- ▶ **Offset:** Allows you to specify inside or outside.
- ▶ **Feed:** Establishes the rate at which the tool will feed along the X, Y plane.

Start Angle

Establishes the starting angle along the circumference of the Helix. Zero degrees is at 3 o'clock. No angle defaults to zero degrees.



Helix		
Center	X	Abs
	Y	Abs
Z	Begin	0.1000 Abs
	End	-0.5200 Abs
Radius		
Direction	CW	
Revolutions		Rev/in
		Revs
Tool	0.2500	Inch
		Type
Offset	Inside	
Feed	10.0	IPM

Radial Slot

The CIRCLE key activates a pop up list of circle features. Highlight the Radial Slot option and press ENTER or press 5 on the keypad to select Radial Slot.



Radial Slot allows you to define a complete stand alone Radial Slot. This step is capable of running in both DRO and PGM mode.

Center

X1 Y1 define the center point of the Radial Slot. This can be cartesian or polar, absolute (ABS) or incremental (INC) from an external reference point.

Z

- ▶ **Begin** is where the tool will rapid to. From there it will feed at the given rate to the End value at the **Feed** provided.
- ▶ This feed is for the Z axis only.
- ▶ **Pass** will divide the operation by the number of times or by the distance you program providing multiple passes to final depth.



Radial Slot			
1st Arc Center		Type	
X1	<input type="text"/>	Abs	<input type="text" value="Pocket"/>
Y1	<input type="text"/>	Abs	
2nd Arc Center		Sweep Angle	
X2	<input type="text"/>	Abs	<input type="text"/>
Y2	<input type="text"/>	Abs	
Z		Tool	
Begin	<input type="text" value="0.1000"/>	Abs	<input type="text" value="0.2500"/> Inch
End	<input type="text" value="-0.0200"/>	Abs	<input type="text"/> Type
Pass	<input type="text"/>	Number	<input type="text" value="10.0"/> IPM
Feed	<input type="text" value="10.0"/>	IPM	
Radius		Center	
	<input type="text"/>	X	<input type="text"/> Abs
		Y	<input type="text"/> Abs
Direction		Finish	
	<input type="text" value="CCW"/>	Bottom	<input type="text" value="0.0000"/>
		Side	<input type="text" value="0.0000"/>
		Feed	<input type="text" value="0.0"/> IPM
Slot Width		Direction	
	<input type="text"/>		<input type="text" value="CCW"/>
		Stepover	
			<input type="text" value="50"/> %

Radial Slot

Radius

Establishes the arc radius of the slot.

Direction

Establishes the sweep direction of the radial slot.

Slot Width


Establishes the width of the radial slot. It must be wider than the tool indicated.

Start Angle


Establishes the start of the radial slot.

Sweep Angle

Establishes the angular length relative to the start angle.



Radial Slot			
1st Arc Center		Type	
X1	<input type="text"/>	Abs	Pocket
Y1	<input type="text"/>	Abs	
2nd Arc Center		Sweep Angle	
X2	<input type="text"/>	Abs	<input type="text"/>
Y2	<input type="text"/>	Abs	
Z		Tool	
Begin	<input type="text" value="0.1000"/>	Abs	0.2500 Inch
End	<input type="text" value="-0.0200"/>	Abs	
Pass	<input type="text"/>	Number	Type
Feed	<input type="text" value="10.0"/>	IPM	Feed
		10.0 IPM	
Radius		Center	
<input type="text"/>		X	<input type="text"/>
		Y	<input type="text"/>
Direction		Finish	
CCW		Bottom	<input type="text" value="0.0000"/>
		Side	<input type="text" value="0.0000"/>
Slot Width		Feed	<input type="text" value="0.0"/>
<input type="text"/>		Direction	CCW
		Stepover	
		<input type="text" value="50"/> %	



Radial Slot

Tool

Shows the tool information of the last tool programmed to insure you the correct tool will be used.

Feed

Establishes the X, Y feed rate.

Finish


Establishes the amount of stock on the Bottom and Side to leave for the final finish pass along with the Feed rate and Direction to use.

Stepover

Allows you to define the percentage of the tool to use per pass for the roughing cut. The default is 50%.

Type

Allows you to choose contour if you wish to use the shape to define an Island within a custom pocket.



Radial Slot			
1st Arc Center		Type	
X1	<input type="text"/>	Abs	<input type="text" value="Pocket"/>
Y1	<input type="text"/>	Abs	
2nd Arc Center		Sweep Angle	
X2	<input type="text"/>	Abs	<input type="text"/>
Y2	<input type="text"/>	Abs	
Z		Tool	
Begin	<input type="text" value="0.1000"/>	Abs	<input type="text" value="0.2500"/> Inch
End	<input type="text" value="-0.0200"/>	Abs	Type
Pass	<input type="text"/>	Number	Feed <input type="text" value="10.0"/> IPM
Feed	<input type="text" value="10.0"/>	IPM	
Radius		Center	
	<input type="text"/>	X	<input type="text"/> Abs
Direction		Y	<input type="text"/> Abs
	<input type="text" value="CCW"/>		
Slot Width		Finish	
	<input type="text"/>	Bottom	<input type="text" value="0.0000"/>
		Side	<input type="text" value="0.0000"/>
		Feed	<input type="text" value="0.0"/> IPM
		Direction	<input type="text" value="CCW"/>
		Stepover	
		<input type="text" value="50"/>	%

Rectangle Pocket

The Rectangle key activates a pop up list of rectangular features. Highlight the Pocket option and press ENTER or press 7 on the keypad to select Pocket.

Rectangle pocket allows you to define a complete stand alone rectangular pocket. This step is capable of running in both DRO and PGM mode.



1st Corner

X1 Y1 defines the anchor point of the rectangle. This can be cartesian or polar, absolute (ABS) or incremental (INC) from an external reference point. An angle entered under More below will pivot upon this corner. Do not enter if a center point is to be entered.

Size

X Y defines the length and width of the rectangle. Values can be positive and negative. Do not enter if using a 2nd Corner.

2nd Corner

X2 Y2 defines a second anchor point of the rectangle. This can be cartesian or polar, absolute (ABS) or an incremental (INC) move from an external reference point. With a given angle the corners remain fixed.

Z

- ▶ **Begin** is where the tool will rapid to. From there it will feed at the given rate to the **End** value stopping for each pass.
- ▶ This feed is for the Z axis only.
- ▶ **Pass** establishes the number of cuts between the Z Begin and End.
- ▶ **Feed** establishes the Z rate of motion for the Z axis only. The feed below is for the X, Y plane.



Rectangle			
1st Corner		Tool	
X1	<input type="text"/>	Abs	<input type="text" value="0.2500"/> Inch
Y1	<input type="text"/>	Abs	<input type="text"/> Type
Size		Feed	<input type="text" value="10.0"/> IPM
X	<input type="text"/>	Center	
Y	<input type="text"/>	X	<input type="text"/> Abs
2nd Corner		Y	<input type="text"/> Abs
X2	<input type="text"/>	Angle	
Y2	<input type="text"/>	<input type="text" value="0.0000"/>	
Z		Finish	
Begin	<input type="text" value="0.1000"/> Abs	Bottom	<input type="text" value="0.0000"/>
End	<input type="text" value="-0.0200"/> Abs	Side	<input type="text" value="0.0000"/>
Pass	<input type="text" value="2"/> Number	Feed	<input type="text" value="0.0"/> IPM
Feed	<input type="text" value="10.0"/> IPM	Direction	<input type="text" value="CCW"/>
Corner		Stepover	
Blend	<input type="text"/> Radius	<input type="text" value="50"/> %	
Direction		Type	
<input type="text" value="CCW"/>		<input type="text" value="Pocket"/>	

Rectangle Pocket

Corner Blend Radius

Establishes the radius of each corner. Left blank and the tools radius will be left at each corner.

Direction

Establishes clockwise (CW) or counter clockwise (CCW) direction for the rough cut.


Tool

▶ Cannot be changed here but shows the tool information of the last tool step programmed to insure you the correct tool will be used.

▶ **Feed** establishes the rate at which the tool will feed along the X, Y plane.

Center

X Y define the center point of the rectangle. This can be cartesian or polar, absolute (ABS) or incremental (INC) from an external reference point. Do not program a first corner or second corner if you plan to use a center value.




Rectangle			
1st Corner		Tool	
X1	<input type="text"/>	Abs	<input type="text" value="0.2500"/> Inch
Y1	<input type="text"/>	Abs	<input type="text"/> Type
Size		Feed	
X	<input type="text"/>	<input type="text" value="10.0"/> IPM	
Y	<input type="text"/>	Center	
2nd Corner		X <input type="text"/> Abs	
X2	<input type="text"/>	Y <input type="text"/> Abs	
Y2	<input type="text"/>	Angle	
Z		<input type="text" value="0.0000"/>	
Begin	<input type="text" value="0.1000"/> Abs	Finish	
End	<input type="text" value="-0.0200"/> Abs	Bottom	<input type="text" value="0.0000"/>
Pass	<input type="text" value="2"/> Number	Side	<input type="text" value="0.0000"/>
Feed	<input type="text" value="10.0"/> IPM	Feed	<input type="text" value="0.0"/> IPM
Corner		Direction <input type="text" value="CCW"/>	
Blend	<input type="text"/>	Stepover	
Radius	<input type="text"/>	<input type="text" value="50"/> %	
Direction		Type	
<input type="text" value="CCW"/>		<input type="text" value="Pocket"/>	



Rectangle Pocket

Angle

Pivots the rectangle as shown.



1st Corner		Tool	
X1	<input type="text"/>	Abs	<input type="text" value="0.2500"/> Inch
Y1	<input type="text"/>	Abs	<input type="text"/> Type
Size	<input type="text"/>	Feed	<input type="text" value="10.0"/> IPM
X	<input type="text"/>	Center	<input type="text"/>
		X	<input type="text"/> Abs
		Y	<input type="text"/> Abs
		File	<input type="text" value="0.0000"/>
		Sh	<input type="text"/>
		Bottom	<input type="text" value="0.0000"/>
		Side	<input type="text" value="0.0000"/>
		Feed	<input type="text" value="0.0"/> IPM
		Direction	CCW
		Power	<input type="text" value="50"/> %
		Mode	Pocket



Rectangle Pocket

Finish

- Establishes the amount of stock (cut) to leave for the final finish pass

- Feed rate and Direction to use

Stepover

Allows you to define the percentage of the tool to use per pass for the roughing cut. The default is 50%.

Type

Allows you to choose contour if you wish to use the shape to define an Island within a custom pocket.



Rectangle			
1st Corner		Tool	
X1	<input type="text"/>	Abs	<input type="text" value="0.2500"/> Inch
Y1	<input type="text"/>	Abs	<input type="text"/> Type
Size		Feed <input type="text" value="10.0"/> IPM	
X	<input type="text"/>	Center	
Y	<input type="text"/>	X	<input type="text"/> Abs
2nd Corner		Y	<input type="text"/> Abs
X2	<input type="text"/>	Angle	
Y2	<input type="text"/>	<input type="text" value="0.0000"/>	
Z		Finish	
Begin	<input type="text" value="0.1000"/> Abs	Bottom	<input type="text" value="0.0000"/>
End	<input type="text" value="-0.0200"/> Abs	Side	<input type="text" value="0.0000"/>
Pass	<input type="text" value="2"/> Number	Feed	<input type="text" value="0.0"/> IPM
Feed	<input type="text" value="10.0"/> IPM	Direction	<input type="text" value="CCW"/>
Corner		Stepover	
Blend	<input type="text"/> Radius	<input type="text" value="50"/> %	
Direction		Type	
<input type="text" value="CCW"/>		<input type="text" value="Pocket"/>	

Rectangle Frame

The Rectangle key activates a pop up list of rectangular features. Highlight the Frame option and press ENTER or press 8 on the keypad to select Frame.

Rectangle Frame allows you to define a complete stand alone rectangular frame. This step is capable of running in both DRO and PGM mode.



1st Corner

X1 Y1 defines the anchor point of the rectangle. This can be cartesian or polar, absolute (ABS) or incremental (INC) from an external reference point. An angle entered under More below will pivot upon this corner. Do not fill in if a center point is to be entered.

Size

X Y defines the length and width of the rectangle. Values can be positive and negative as needed. Do not enter values if using a second corner.

2nd Corner

X2 Y2 can be used to define a second anchor point for the rectangle. This can be cartesian or polar, absolute (ABS) or incremental (INC) from an external reference point. With a given angle the corners remain fixed.

Z

- ▶ **Begin** is where the tool will rapid to. From there it will **Feed** at the given rate to the End value stopping for each pass.
- ▶ **Pass** establishes the number of cuts between the Z Begin and End.
- ▶ **Feed** establishes the Z rate of motion for the Z axis only. The feed below is for the X, Y plane.



Rectangle Frame			
1st Corner	X1 <input type="text"/>	Abs	Tool
	Y1 <input type="text"/>	Abs	
Size	X <input type="text"/>		<input type="text" value="0.2500"/> Inch
	Y <input type="text"/>		<input type="text"/> Type
			Offset <input type="text" value="Center"/>
			Feed <input type="text" value="10.0"/> IPM
2nd Corner	X2 <input type="text"/>	Abs	Center
	Y2 <input type="text"/>	Abs	
Z	Begin <input type="text" value="0.1000"/>	Abs	Angle
	End <input type="text" value="-0.0200"/>	Abs	
	Pass <input type="text" value="2"/>	Number	
	Feed <input type="text" value="10.0"/>	IPM	
Corner	Blend <input type="text"/>	Radius	Finish
Direction	<input type="text" value="CCW"/>		
			<input type="text" value="0.0000"/> Cut
			Feed <input type="text" value="0.0"/> IPM
			Direction <input type="text" value="CCW"/>

Rectangle Frame



Corner Blend Radius

Establishes the radius of each corner. Left blank and the tools radius will be left at each corner. Chamfer can also be selected here.

Direction

Establishes clockwise (CW) or counter clockwise (CCW) direction for the rough cut.

Tool

▶ Cannot be changed here but shows the tool information of the last tool step programmed to insure you the correct tool will be used.

▶ **Feed** establishes the rate at which the tool will feed along the X, Y plane.

Center

X Y define the center point of the rectangle. This can be cartesian or polar, absolute (ABS) or incremental (INC) from an external reference point. Do not program a first corner or second corner if you plan to use a center value.

Angle

Pivots the rectangle as shown earlier.

Finish

▶ Establishes the amount of stock (cut) to leave for the final finish pass


▶ **Feed** rate and **Direction** to use

Rectangle Frame			
1st Corner	X1 <input type="text"/>	Abs	Tool
	Y1 <input type="text"/>	Abs	
Size	X <input type="text"/>		<input type="text" value="0.2500"/> Inch
	Y <input type="text"/>		<input type="text"/> Type
2nd Corner	X2 <input type="text"/>	Abs	Offset <input type="text" value="Center"/>
	Y2 <input type="text"/>	Abs	Feed <input type="text" value="10.0"/> IPM
Z	Begin <input type="text" value="0.1000"/>	Abs	Center
	End <input type="text" value="-0.0200"/>	Abs	X <input type="text"/>
	Pass <input type="text" value="2"/>	Number	Y <input type="text"/>
	Feed <input type="text" value="10.0"/>	IPM	Angle
Corner	Blend <input type="text"/>	Radius	<input type="text" value="0.0000"/>
Direction	<input type="text" value="CCW"/>		Finish
			Feed <input type="text" value="0.0000"/> Cut
			Feed <input type="text" value="0.0"/> IPM
			Direction <input type="text" value="CCW"/>

Rectangle Face

The Rectangle key activates a pop up list of rectangular features. Highlight the Face option and press ENTER or press 9 on the keypad to select Face.

Rectangle Face allows you to define a complete stand alone rectangular facing operation. This step is capable of running in both DRO and PGM mode..



1st Corner

X1 Y1 defines the start point of the facing operation. This can be cartesian or polar, absolute (ABS) or incremental (INC) from an external reference point.

Size

X Y defines the length and width of the rectangle. Values can be positive and negative as needed. Do not use if using a second corner.

2nd Corner

X2 Y2 can be used to define a second anchor point of the rectangle. This can be cartesian or polar, absolute (ABS) or incremental (INC) from an external reference point. With a given angle the corners remain fixed.

Z

- ▶ **Begin** is where the tool will rapid to. From there it will feed at the given rate to the **End** value stopping for each pass.
- ▶ **Pass** establishes the number of cuts between the Z Begin and End.
- ▶ **Feed** establishes the Z rate of motion for the Z axis only. The feed below is for the X, Y plane.



Face					
1st Corner		Center			
X1	<input type="text"/>	Abs	X	<input type="text"/>	Abs
Y1	<input type="text"/>	Abs	Y	<input type="text"/>	Abs
Size		Angle			
X	<input type="text"/>			<input type="text" value="0.0000"/>	
Y	<input type="text"/>				
2nd Corner		Stepover			
X2	<input type="text"/>	Abs	<input type="text" value="50"/>		%
Y2	<input type="text"/>	Abs	Tool Path Priority		
Z		<input type="text" value="Shortest Path"/>			
Begin	<input type="text" value="0.1000"/>	Abs			
End	<input type="text" value="-0.0200"/>	Abs			
Pass	<input type="text" value="2"/>	Number			
Feed	<input type="text" value="10.0"/>	IPM			
Tool					
	<input type="text" value="0.2500"/>	Inch			
	<input type="text"/>	Type			
Feed	<input type="text" value="10.0"/>	IPM			

Rectangle Face

Tool

- ▶ Cannot be changed here but shows the tool information of the last tool step programmed to insure you the correct tool will be used.
- ▶ **Feed** establishes the rate at which the tool will feed along the X, Y plane.

Center

X Y define the center point of the rectangle. This can be cartesian or polar, absolute (ABS) or incremental (INC) from an external reference point. Do not program a first corner or second corner if you plan to use a center value.

Angle

Pivots the rectangle as described earlier.

Stepover

Allows you to define the percentage of the tool to use per pass for the roughing cut. The default is 50%.

Tool Path Priority

Allows you select either the shortest path or select even spacing over across the face.




Face		
1st Corner		Center
X1	<input type="text"/>	Abs
Y1	<input type="text"/>	Abs
Size		Angle
X	<input type="text"/>	<input type="text" value="0.0000"/>
Y	<input type="text"/>	
2nd Corner		Stepover
X2	<input type="text"/>	<input type="text" value="50"/> %
Y2	<input type="text"/>	Tool Path Priority
		<input type="text" value="Shortest Path"/>
Z		
Begin	<input type="text" value="0.1000"/>	Abs
End	<input type="text" value="-0.0200"/>	Abs
Pass	<input type="text" value="2"/>	Number
Feed	<input type="text" value="10.0"/>	IPM
Tool		
	<input type="text" value="0.2500"/>	Inch
	<input type="text"/>	Type
Feed	<input type="text" value="10.0"/>	IPM

Rectangle Slot

The Rectangle key activates a pop up list of rectangular features. Highlight the Slot option and press ENTER or press 4 on the keypad to select Slot.

Rectangle Slot allows you to define a complete stand alone rectangular slot. This step is capable of running in both DRO and PGM mode.



1st Arc Center

X1 Y1 defines the anchor point of the slot. This can be cartesian or polar, absolute (ABS) or incremental (INC) from an external reference point. An angle entered under More below will pivot upon this corner. Do not fill in if a center point is to be entered.

2nd Arc Center


X2 Y2 can be used to define a second anchor point for the slot. This can be cartesian or polar, absolute (ABS) or incremental (INC) from an external reference point. When both centers are entered the angle is calculated.

Z

- ▶ **Begin** is where the tool will rapid to before feeding at the given rate to the **End** value stopping for each pass.
- ▶ **Pass** establishes the number of cuts between the Z Begin and End.
- ▶ **Feed** establishes the Z rate of motion for the Z axis only. The feed below is for the X, Y plane.

Direction

Establishes clockwise (CW) or counter clockwise (CCW) direction for the rough cut.



Slot	
1st Arc Center	Tool
X1 <input type="text"/>	<input type="text" value="0.2500"/> Inch
Y1 <input type="text"/>	<input type="text"/> Type
	Feed <input type="text" value="10.0"/> IPM
2nd Arc Center	Center
X2 <input type="text"/>	X <input type="text"/>
Y2 <input type="text"/>	Y <input type="text"/>
Z	Angle
Begin <input type="text" value="0.1000"/> Abs	<input type="text" value="0.0000"/>
End <input type="text" value="-0.0200"/> Abs	
Pass <input type="text"/>	Finish
Feed <input type="text" value="10.0"/> IPM	Bottom <input type="text" value="0.0000"/>
Direction	Side <input type="text" value="0.0000"/>
<input type="text" value="CCW"/>	Feed <input type="text" value="0.0"/> IPM
Slot Width	Direction <input type="text" value="CCW"/>
<input type="text"/>	Stepover
Slot Length	<input type="text" value="50"/> %
<input type="text"/>	Type
	<input type="text" value="Pocket"/>

Rectangle Slot

Slot Width

Establishes how wide the slot will be.

Slot Length

Establishes how long the slot will be.

Tool

- ▶ Displays the tool information of the last tool step to insure you the correct tool will be used.
- ▶ **Feed:** Establishes the feed rate along the X, Y plane.

Center

X Y define the center point of the slot. This can be cartesian or polar, absolute (ABS) or incremental (INC) from an external reference point. Do not program a first corner or second corner if you plan to use a center value.

Angle

Pivots the slot as shown earlier.

Finish


Establishes the amount of stock (cut) to leave for the final finish pass along with the feed rate and direction to use.

Stepover

Allows you to define the percentage of the tool to use per pass for the roughing cut. The default is 50%.

Type

Allows you to choose contour if you wish to use the shape to define an Island within a custom pocket.



Slot	
1st Arc Center	Tool
X1 <input type="text"/>	<input type="text" value="0.2500"/> Inch
Y1 <input type="text"/>	<input type="text"/> Type
	Feed <input type="text" value="10.0"/> IPM
2nd Arc Center	Center
X2 <input type="text"/>	X <input type="text"/>
Y2 <input type="text"/>	Y <input type="text"/>
Z	Angle
Begin <input type="text" value="0.1000"/> Abs	<input type="text" value="0.0000"/>
End <input type="text" value="-0.0200"/> Abs	
Pass <input type="text"/>	Finish
Feed <input type="text" value="10.0"/> IPM	Bottom <input type="text" value="0.0000"/>
Direction	Side <input type="text" value="0.0000"/>
<input type="text" value="CCW"/>	Feed <input type="text" value="0.0"/> IPM
Slot Width	Direction <input type="text" value="CCW"/>
<input type="text"/>	Stepover
Slot Length	<input type="text" value="50"/> %
<input type="text"/>	Type
	<input type="text" value="Pocket"/>


Rectangle Slot

Slot Width


- ▶ Center, width, Length, Angle.
- ▶ 1st Arc Center, 2nd Arc Center, Width.
- ▶ 1st Arc Center, Width, Length, Angle.

Requirements


1. Length and width must be positive values.
2. Width must be less than length.




Programmed from arc centers




Adjustment to size does not change the arc center locations



Programmed center, length and width



Adjustment to size does not change the arc center locations



Row of Holes

The HOLES key activates a pop up list of Hole features. Highlight the Row of Holes option and press ENTER or press 7 on the keypad to select Row of Holes. Row of Holes

allows you to define a complete stand alone Row of Holes. This step is capable of running in both DRO and PGM mode.



From

X1 Y1 define the start point of the row. These can be cartesian or polar, absolute (ABS) or incremental (INC) from an external reference point.

To

X2 Y2 is the end of the row and can be cartesian or polar, absolute (ABS) or incremental (INC) from the begin point or an external reference point. Do not enter if using Hole Spacing.

Z

- ▶ **Begin** is where the tool will rapid to. From there it will feed at the given rate to the **End** value at the Feed provided.
- ▶ This feed is for the Z axis only.
- ▶ When finished, the tool then rapids up to the retract plane set in datum.
- ▶ **Peck** lifts the tool slightly breaking the chip then resuming.
- ▶ Choosing **Drill** feeds down and rapids up, Bore feeds in both directions, and **Position** causes the routine to work as a two axis operation pausing at each location until GO is pressed.

Holes

Establishes the number of holes in the row.



Row of Holes			
From	X1 <input type="text"/>	Abs	Tool Retract
	Y1 <input type="text"/>	Abs	Dwell <input type="text"/> Number <input type="text"/> Sec
To	X2 <input type="text"/>	Abs	Tool
	Y2 <input type="text"/>	Abs	<input type="text"/> 0.2500 <input type="text"/> Inch <input type="text"/> Type
Z	Begin <input type="text"/> 0.1000	Abs	Tool
	End <input type="text"/> -0.0200	Abs	Dwell <input type="text"/> Sec
	Peck <input type="text"/>	Number	
	<input type="text"/> Drill		
	Feed <input type="text"/> 10.0	IPM	
Holes	<input type="text"/>		
Hole Spacing	<input type="text"/> Between		
Angle	<input type="text"/>		

Row of Holes

Hole Spacing

Can be used alternatively to the **To** point. When used the **To** is calculated and is best used along with angle.

Angle

Allows you to create a row by programming along an angle using a **From** point, number of holes, spacing, and angle.

Tool Retract

Establishes the number of times the tool will lift to the Z begin. When here it will dwell for the time entered in seconds before resuming allowing the tool and work to cool. The retract can be programmed along with peck to create the optimum drilling cycle.

Tool

Cannot be changed here but shows the tool information of the last tool step programmed to insure you the correct tool will be used. Displays information of the last tool step programmed to insure you the correct tool will be used.

Dwell

Holds the tool at the Z End for the number of seconds (Sec) provided to finish the bottom of the holes.




Row of Holes			
From	X1 <input type="text"/>	Abs	Tool Retract
	Y1 <input type="text"/>	Abs	Dwell <input type="text"/>
To	X2 <input type="text"/>	Abs	Tool
	Y2 <input type="text"/>	Abs	<input type="text" value="0.2500"/>
Z	Begin <input type="text" value="0.1000"/>	Abs	Tool
	End <input type="text" value="-0.0200"/>	Abs	Dwell <input type="text"/>
	Peck <input type="text"/>	Number	
	Drill <input type="text" value="Drill"/>		
	Feed <input type="text" value="10.0"/>	IPM	
Holes	<input type="text"/>		
Hole Spacing	<input type="text"/>	Between	
Angle	<input type="text"/>		

Rectangle Frame of Holes

The HOLES key activates a pop up list of Hole features. Highlight the Rectangle Frame option and press ENTER or press 8 on the keypad to select Rectangle Frame.

Rectangle Frame allows you to define a complete stand alone Rectangle Frame of holes. This step is capable of running in both DRO and PGM mode.



1st Corner

X1 Y1 defines the anchor point of the rectangular hole pattern. This can be cartesian or polar, absolute (ABS) or incremental (INC) from an external reference point. An angle entered under More below will pivot upon this corner. Do not fill in if a center point is to be entered.

Size

X Y defines the length and width of the rectangle and can be positive and negative as needed. Do not use if using a second corner or Hole Spacing is to be entered.




Hole Frame			
1st Corner		Hole Spacing	
X1	<input type="text"/>	Abs	X <input type="text"/>
Y1	<input type="text"/>	Abs	Y <input type="text"/>
Size		Center	
X	<input type="text"/>	X	<input type="text"/>
Y	<input type="text"/>	Y	<input type="text"/>
2nd Corner		Angle	
X2	<input type="text"/>	Abs	<input type="text" value="0.0000"/>
Y2	<input type="text"/>	Abs	
Z		Tool Retract	
Begin	<input type="text"/>	Abs	<input type="text"/>
End	<input type="text" value="0.0000"/>	Abs	Dwell <input type="text"/>
Peck	<input type="text"/>	Number	Tool
	<input type="text" value="Drill"/>		<input type="text" value="0.2500"/>
Feed	<input type="text" value="10.0"/>	IPM	Type <input type="text"/>
Holes		Tool	
X	<input type="text"/>	Dwell	<input type="text"/>
Y	<input type="text"/>		Sec

Rectangle Frame of Holes

The HOLES key activates a pop up list of Hole features. Highlight the Rectangle Frame option and press ENTER or press 8 on the keypad to select Rectangle Frame.

Rectangle Frame allows you to define a complete stand alone Rectangle Frame of holes. This step is capable of running in both DRO and PGM mode.



1st Corner

X1 Y1 defines the anchor point of the rectangular hole pattern. This can be cartesian or polar, absolute (ABS) or incremental (INC) from an external reference point. An angle entered under More below will pivot upon this corner. Do not fill in if a center point is to be entered.

Size

X Y defines the length and width of the rectangle and can be positive and negative as needed. Do not use if using a second corner or Hole Spacing is to be entered.



Hole Frame			
1st Corner		Hole Spacing	
X1	<input type="text"/>	Abs	X <input type="text"/>
Y1	<input type="text"/>	Abs	Y <input type="text"/>
Size		Center	
X	<input type="text"/>	X	<input type="text"/>
Y	<input type="text"/>	Y	<input type="text"/>
2nd Corner		Angle	
X2	<input type="text"/>	Abs	<input type="text" value="0.0000"/>
Y2	<input type="text"/>	Abs	
Z		Tool Retract	
Begin	<input type="text"/>	Abs	<input type="text"/>
End	<input type="text" value="0.0000"/>	Abs	Dwell <input type="text"/>
Peck	<input type="text"/>	Number	
	<input type="text" value="Drill"/>		
Feed	<input type="text" value="10.0"/>	IPM	Tool <input type="text" value="0.2500"/>
Holes		Tool	
X	<input type="text"/>	Dwell	<input type="text"/>
Y	<input type="text"/>		Sec

Rectangle Frame of Holes



2nd Corner

X2 Y2 can be used to define a second anchor point of the rectangle. This can be cartesian or polar, absolute (ABS) or incremental (INC) from an external reference point. When used with first corner, hole spacing will be calculated. With a given angle the corners remain fixed.

Z

- ▶ **Begin** is where the tool will rapid to. From there it will feed at the given rate to the **End** value at the Feed provided.
- ▶ This feed is for the Z axis only.
- ▶ When finished, the tool then rapids up to the retract plane set in datum.
- ▶ **Peck**: Lifts the tool slightly breaking the chip then resuming.
- ▶ There are three drilling options. Choosing **Drill** feeds down and rapids up, **Bore** feeds in both directions, and **Position** causes the routine to work as a two axis operation pausing at each location until GO is pressed.

Hole Spacing

Can be used alternatively to the To point. When entered, the To point is calculated. This option makes setting a frame on an angle simple.

Center

X Y define the center point of the rectangle. This can be cartesian or polar, absolute (ABS) or incremental (INC) from an external reference point. Do not program a first corner or second corner when using a center location.

Hole Frame			
1st Corner		Hole Spacing	
X1	<input type="text"/>	Abs	X <input type="text"/>
Y1	<input type="text"/>	Abs	Y <input type="text"/>
Size		Center	
X	<input type="text"/>	X	<input type="text"/>
Y	<input type="text"/>	Y	<input type="text"/>
2nd Corner		Angle	
X2	<input type="text"/>	Abs	<input type="text" value="0.0000"/>
Y2	<input type="text"/>	Abs	
Z		Tool Retract	
Begin	<input type="text"/>	Abs	<input type="text"/>
End	<input type="text" value="0.0000"/>	Abs	Dwell <input type="text"/>
Peck	<input type="text"/>	Number	
	<input type="text" value="Drill"/>		Tool
Feed	<input type="text" value="10.0"/>	IPM	<input type="text" value="0.2500"/>
			<input type="text"/>
Holes		Tool	
X	<input type="text"/>	Dwell	<input type="text"/>
Y	<input type="text"/>		Sec

Rectangle Frame of Holes



Angle

Allows you to define the frame by programming along an angle using a From Point or Center, Number of Holes, Hole Spacing, and Angle.

Tool Retract

Establishes the number of times the tool will lift to the Z begin. When there it can dwell for the time entered in seconds (Sec) before re-suming, allowing the tool and work to cool. The retract can be programmed along with peck to create the optimum drilling cycle.

Tool

Cannot be changed here but shows the tool information of the last tool step programmed to insure you the correct tool will be used.

Dwell

Holds the tool at the Z End for the number of seconds (Sec) provided to finish the bottom of each hole.

Hole Frame			
1st Corner		Hole Spacing	
X1	<input type="text"/>	Abs	X <input type="text"/>
Y1	<input type="text"/>	Abs	Y <input type="text"/>
Size		Center	
X	<input type="text"/>	X	<input type="text"/>
Y	<input type="text"/>	Y	<input type="text"/>
2nd Corner		Angle	
X2	<input type="text"/>	Abs	<input type="text" value="0.0000"/>
Y2	<input type="text"/>	Abs	
Z		Tool Retract	
Begin	<input type="text"/>	Abs	<input type="text"/>
End	<input type="text" value="0.0000"/>	Abs	Dwell <input type="text"/>
Peck	<input type="text"/>	Number	
	<input type="text" value="Drill"/>		
Feed	<input type="text" value="10.0"/>	IPM	
Holes		Tool	
X	<input type="text"/>	Dwell	<input type="text"/>
Y	<input type="text"/>		
			<input type="text" value="0.2500"/>
			Inch Type
			<input type="text"/>
			Sec


Rectangle Array of Holes

The HOLES key activates a pop up list of Hole features. Highlight the Rectangle Array option and press ENTER or press 9 on the keypad to select Rectangle Array. Rectangle

Array allows you to define a complete stand alone Rectangle Array of holes.

This step is capable of running in both DRO and PGM mode.

- 7 Row of Holes
- 8 Rectangle Frame
- 9 **Rectangle Array**
- 4 Bolt Circle



1st Corner

X1 Y1 defines the anchor point of the rectangular hole Array. This can be cartesian or polar, absolute (ABS) or incremental (INC) from an external reference point. An angle entered under More below will pivot upon this corner. Do not fill in if a center point is to be entered.

Size

X Y defines the length and width of the rectangle and can be positive and negative as needed. Do not use if using a second corner or Hole Spacing is to be entered.



Hole Array			
1st Corner		Hole Spacing	
X1	<input type="text"/>	Abs	X <input type="text"/>
Y1	<input type="text"/>	Abs	Y <input type="text"/>
Size		Center	
X	<input type="text"/>	X	<input type="text"/>
Y	<input type="text"/>	Y	<input type="text"/>
2nd Corner		Angle	
X2	<input type="text"/>	Abs	<input type="text" value="0.0000"/>
Y2	<input type="text"/>	Abs	
Z		Tool Retract	
Begin	<input type="text"/>	Abs	<input type="text"/>
End	<input type="text" value="0.0000"/>	Abs	Dwell <input type="text"/>
Peck	<input type="text"/>	Number	
	<input type="text" value="Drill"/>		
Feed	<input type="text" value="10.0"/>	IPM	Tool
			<input type="text" value="0.2500"/>
			Inch
			Type
Holes		Tool	
X	<input type="text"/>	Dwell	<input type="text"/>
Y	<input type="text"/>		Sec

Rectangle Array of Holes



2nd Corner

X2 Y2 can be used to define a second anchor point of the rectangle. This can be cartesian or polar, absolute (ABS) or incremental (INC) from an external reference point. When used with first corner, hole spacing will be calculated. With a given angle the corners remain fixed.

Z

- ▶ **Begin** is where the tool will rapid to. From there it will feed at the given rate to the **End** value at the Feed provided.
- ▶ This feed is for the Z axis only. When finished, the tool then rapids up to the retract plane set in datum.
- ▶ **Peck**: Lifts the tool slightly breaking the chip then resuming.
- ▶ There are three drilling options. Choosing **Drill** feeds down and rapids up, **Bore** feeds in both directions, and **Position** causes the routine to work as a two axis operation pausing at each location until GO is pressed.

Holes

X Y establishes the number of holes in the X and Y Array.

Hole Spacing

Can be used alternatively to the To point. When entered, the To point is calculated. This option makes setting an Array on an angle simple.

Center

X Y define the center point of the array. This can be cartesian or polar, absolute (ABS) or incremental (INC) from an external reference point. Do not program a first corner or second corner if you plan to use a center value.

Hole Array			
1st Corner		Hole Spacing	
X1	<input type="text"/>	Abs	X <input type="text"/>
Y1	<input type="text"/>	Abs	Y <input type="text"/>
Size		Center	
X	<input type="text"/>	X	<input type="text"/>
Y	<input type="text"/>	Y	<input type="text"/>
2nd Corner		Angle	
X2	<input type="text"/>	Abs	<input type="text" value="0.0000"/>
Y2	<input type="text"/>	Abs	
Z		Tool Retract	
Begin	<input type="text"/>	Abs	<input type="text"/>
End	<input type="text" value="0.0000"/>	Abs	Dwell <input type="text"/>
Peck	<input type="text"/>	Number	
Feed	<input type="text" value="10.0"/>	IPM	Tool
			<input type="text" value="0.2500"/>
			Inch Type
Holes		Tool	
X	<input type="text"/>	Dwell	<input type="text"/>
Y	<input type="text"/>		Sec

Rectangle Array of Holes

Angle

Allows you to define the array by programming along an angle using a From Point or Center, Number of Holes, Hole Spacing, and Angle.

Tool Retract

Establishes the number of times the tool will lift to the Z begin. When there it can dwell for the time entered in seconds (Sec) before re-suming, allowing the tool and work to cool. The retract can be programmed along with peck to create the optimum drilling cycle.

Tool

Cannot be changed here but shows the tool information of the last tool step programmed to insure you the correct tool will be used.

Dwell

Holds the tool at the Z End for the number of seconds (Sec) provided to finish the bottom of each hole.



Hole Array			
1st Corner		Hole Spacing	
X1	<input type="text"/>	Abs	X <input type="text"/>
Y1	<input type="text"/>	Abs	Y <input type="text"/>
Size		Center	
X	<input type="text"/>	X	<input type="text"/>
Y	<input type="text"/>	Y	<input type="text"/>
2nd Corner		Angle	
X2	<input type="text"/>	Abs	<input type="text" value="0.0000"/>
Y2	<input type="text"/>	Abs	
Z		Tool Retract	
Begin	<input type="text"/>	Abs	<input type="text"/>
End	<input type="text" value="0.0000"/>	Abs	<input type="text"/>
Peck	<input type="text"/>	Number	
	<input type="text" value="Drill"/>		
Feed	<input type="text" value="10.0"/>	IPM	
Holes		Tool	
X	<input type="text"/>	<input type="text" value="0.2500"/>	Inch
Y	<input type="text"/>	<input type="text"/>	Type
		Tool	
		Dwell	<input type="text"/>
			Sec

Bolt Circle

The HOLES key activates a pop up list of Hole features. Highlight the Bolt Circle option and press ENTER or press 4 on the keypad to select Bolt Circle.

Bolt Circle allows you to define a complete stand alone Bolt Circle. This step is capable of running in both DRO and PGM mode.



Center

X Y define the center point of the Bolt Circle. This can be cartesian or polar, absolute (ABS) or incremental (INC) from an external reference point.

Z

- ▶ **Begin** is where the tool will rapid to before it slows to the Z **feed** provided. When finished, the tool then rapids up to the retract plane set in datum.
- ▶ **Peck**: Lifts the tool slightly breaking the chip then resuming.
- ▶ There are three drilling options. Choosing **Drill** feeds down and rapids up, **Bore** feeds in both directions, and **Position** creates a two axis operation pausing at each location until GO is pressed.

Radius

Establishes the size of the Bolt Hole Pattern.

Holes

Establishes the number of holes in the pattern.

Start Angle

Used to place the first hole along the radius.



Bolt Circle			
Center	X <input type="text"/>	Abs	
	Y <input type="text"/>	Abs	
Z	Begin <input type="text"/>	Abs	
	End <input type="text" value="0.0000"/>	Abs	
	Peck <input type="text"/>	Number	
	Drill <input type="text"/>		
	Feed <input type="text" value="10.0"/>	IPM	
Radius	<input type="text"/>		
Direction	<input type="text" value="CCW"/>		
Holes	<input type="text"/>		
Start Angle	<input type="text" value="0.0000"/>		
	End Angle	<input type="text" value="0.0000"/>	
	Tool Retract	<input type="text"/>	Number
	Dwell	<input type="text"/>	Sec
	Tool	<input type="text" value="0.2500"/>	Inch
		<input type="text"/>	Type
	Tool	<input type="text"/>	Sec
	Dwell	<input type="text"/>	Sec

Bolt Circle

End Angle

Places the last hole along the radius. Leave blank for a full circle pattern.

Tool Retract

Establishes the number of times the tool will lift to the Z begin. When there it can dwell for the time entered in seconds (Sec) before re-suming, allowing the tool and work to cool. The retract can be programmed along with peck to create the optimum drilling cycle.

Tool

Cannot be changed here but shows the tool information of the last tool step programmed to insure you the correct tool will be used.

Dwell

Holds the tool at the Z End for the number of seconds (Sec) provided to finish the bottom of each hole.



Bolt Circle			
Center		End Angle	
X	<input type="text"/>	Abs	<input type="text" value="0.0000"/>
Y	<input type="text"/>	Abs	
Z		Tool Retract	
Begin	<input type="text"/>	Abs	<input type="text"/>
End	<input type="text" value="0.0000"/>	Abs	Number
Peck	<input type="text"/>	Number	Sec
	<input type="text" value="Drill"/>		
Feed	<input type="text" value="10.0"/>	IPM	
Radius		Tool	
	<input type="text"/>	<input type="text" value="0.2500"/>	Inch
Direction		<input type="text"/>	Type
	<input type="text" value="CCW"/>		
Holes		Tool	
	<input type="text"/>	Dwell	<input type="text"/>
Start Angle		Sec	
	<input type="text" value="0.0000"/>		

Blend, Inverted Blend & Chamfer

The BLEND key opens the Blend/Chamfer window allowing you to add a blend radius, inverted radius, or chamfer between two consecutive program steps in a continuous tool path. Chamfer to easily add a radius tangent to two lines and or arcs. The inverted chamfer is useful for leaving stock for a corner hole or to add interest to a profile. Chamfer creates a straight corner transition defined by length and width.

Type

Allows you to select Blend, Blend (Inv), or Chamfer

Steps

From and To indicate the steps to be blended. When inserting a blend between two existing steps, highlight the second of the two program steps. The blend will be inserted between the two. The steps must be continuous.

Radius


Defines the size of the blend. It must be large enough to fit between the features if a gap exists between the two. A blend must be less than 180 degrees.

Contour

Use Open if blending with the next step in the path or choose Closed to blend with the first step in continuous path.

Size

Length 1 and Length 2 define a chamfer. Length 1 is the distance back along the from step starting from the intersecting point of the from and to step and Length 2 is the distance forward along the to step from the intersection.



Blend\Chamfer	
Type	Blend
Steps	From 4 To 2
Radius	
Contour	Closed
Tool	Feed 10.0 IPM


Blend\Chamfer	
Type	Blend
Steps	From 4 To 6
Radius	
Contour	Open
Tool	Feed 10.0 IPM

Program (PGM) Mode

When the DRO / PGM button is pressed the control switches between the digital readout (DRO) and program (PGM) mode. The program mode allows you to assemble multiple steps into a sequential set of operations.

DRO
PGM

1. **Status Bar:** Servo Motor Status, Estimated Time, Tool, Datum, Scale, Skew, (Inch/MM).
2. **Part Graphics:** Display 2D Line, 3D Line or 3D Solid (shown).
3. **Operator Intervention Message:** Prompts for an action required and displays errors.
4. **Soft Keys Display Area:** Indicates the function of the key below.
5. **Program Name**
6. **Program Steps**
7. **Step Range**
8. **Continuous Path Indicator:** Indicates when a tool path is continuous and is open ended or closed loop (shown).




The part graphics can be changed by pressing the view key and using the soft key functions. MILLPWRG2 uses a highlighted cursor to mark a field for selection or editing. The cursor will also change from a highlighted bar to a text cursor when data is entered. Use the ARROWS keys to move the cursor. The UP, DOWN arrows move the cursor through the fields. The RIGHT arrow will open a field that contains more choices, or subfolders in the folder tree. The LEFT arrow will close the menu, or subfolders.

Program (PGM) Mode

When the Program Functions soft key is pressed the view switches to the program management screen. The program management area allows you to load, save, rename, delete and relocate programs. Access programs stored in the console, on a Network, and on USB memory devices. The default storage folder for the console is v:\user\.

Program
Functions

- Soft Keys** change as required for the action you perform.
- Program Graphic Preview** available after a program has been drawn.
- Program Steps Preview** helps identify the program you seek.
- Current Folder** selected indicates which folder you are viewing.
- Status Bar** shows machine status.
- Program List** displays the list of all the programs stored in the current location (as filtered by type).
- Folder View:** Pressing this soft key opens the folder tree window and pressing the Change Window soft key will change the active window switching between Program List, Program Steps Preview, and Folder View. Use Change Window to select which window you would like to navigate.
- Loaded Program:** Shows the name of the program currently loaded.
- Program Type:** Shows the file type filter selected for the folder list.



Program List

Press the Change Window soft key to select the Program List window. When active the background will turn white. With the program list active the following soft keys are available.

Change
Window

The screenshot displays a CNC control interface with a file browser window. The top status bar shows: Stop, Time: 0:05:28, Tool: 0.2500 Inch, Datum: 1, Scale: 1.0000, Skew: 0.0000*, and Inch. The file browser window is titled 'USER:\user\Exercises\ (39)' and shows a tree view on the left with 'Exercises' selected. The main area lists files including 'EXERCISE 1.MPT', 'EXERCISE 2.MPT', 'EXERCISE 3.MPT', 'EXERCISE 4.MPT', 'EXERCISE 5.MPT', 'EXERCISE 6.MPT', 'EXERCISE 7.MPT', 'EXERCISE 8.MPT', and 'EXERCISE 8.DXF.DXF'. A 'MillPWR Text File' window is open, showing parameters: FormatVersion = 3.0, DimensionUnits = INCH, FeedRateUnits = INCH, AngleFormat = DEGREES, Steps = 12, StepOver = 0, and NumberOfCycles = TRUE. The 'Loaded Program:' field shows 'EXERCISE 1.MPT' and 'Program Type:' is 'All files'. A 3D model of a part is visible in the bottom right. The bottom control bar includes keys: Load, Save, Program Type, Function, Select, Change Window, Folder View, and Exit.

Program List

Use the arrow keys to highlight a program then press load to edit and run the program.

Press save to save the current program.

Allows you to filter a large list of programs into

Loaded Program:


Program Type:

7	MILLPWR Programs (.MPT)
8	G-code Programs (.G,.NC)
9	DXF Drawings (.DXF)
4	All Programs (.MPT,.G,.NC,.DXF)
5	All Files

Load Save Program Type Function Select Change Window **Folder View** Exit

- ▶ An arrow on a soft key indicates a list of options.
- ▶ Pressing the keypad number shown next to the option will activate that option.
- ▶ An inactive option is shown faded.
- ▶ An active soft key is shown depressed and with yellow text

Program List



Allows you to cut, copy, paste, rename, delete, and merge programs.

Allows you to select more than one program to copy and paste elsewhere. Clear will unselect all selections.

Will change the active window switching between Program List, Program Steps Preview and Folder View.

Shows and hides the folder view (showing but with program list active in example).

Returns you to the program edit mode.

- ▶ An arrow on a soft key indicates a list of options.
- ▶ Pressing the keypad number shown next to the option will activate that option.
- ▶ An inactive option is shown faded.
- ▶ An active soft key is shown depressed and with yellow text

Folder List

Press the Change Window soft key to select the folder tree window. When active, the background will turn white. The folder tree can be used to access a connection to a network, USB memory devices, or folders on your MILLPWR^{G2}. Navigate through the folders using the up down arrow keys. Expand a folder with the right arrow key, collapse a folder with the left arrow key. Folders can be created on V:\User which is the MILLPWR^{G2} console default folder, on a USB device, on a network, or within sub-folders that have already been created. With the Folder tree window active the following soft keys are available.

Change
Window

Stop Time: 0:05:28 Tool: 0.2500 Inch Datum: 1 Scale: 1.0000 Skew: 0.0000* Inch

USER:\user\Exercises\ (39) Free: 19.3 GB

MILLPWR

- USER:
 - service
 - user
 - Exercises
 - Recycle bin

Example Program G2...	EXERCISE 4.MPT	EXERCISE 6.PNG
Example Program G2...	EXERCISE 4.PNG	EXERCISE 7.MPT
EXERCISE 1.MPT	EXERCISE 5 R8.MPT	EXERCISE 7.PNG
EXERCISE 1.PNG	EXERCISE 5.MPT	EXERCISE 8 .MPT
EXERCISE 2.MPT	EXERCISE 5.PNG	EXERCISE 8 .PNG
EXERCISE 2.PNG	EXERCISE 6 with isla...	EXERCISE 8 DXF.DXF
EXERCISE 3.MPT	EXERCISE 6 with isla...	GEOCALC EXAMPLE...
EXERCISE 3.PNG	EXERCISE 6.MPT	GEOCALC EXAMPLE...

MillPWR Text File


FormatVersion = 3.0
 DimensionUnits = INCH
 FeedRateUnits = INCH
 AngleFormat = DEGREES
 Steps = 12
 StepOver = 0
 NumberOfCycles = TRUE

Loaded Program: EXERCISE 1.MPT
 Program Type: All files

00:05:28

Load Save Program Type Function Select Change Window Folder View Exit

Folder List




After navigating to where you wish to create a new folder, press Create Folder to create a new folder.

Allows you to filter a large list of programs into easy to navigate views segregated by file type.

- ▶ An arrow on a soft key indicates a list of options.
- ▶ Pressing the keypad number shown next to the option will activate that option.
- ▶ An inactive option is shown faded.
- ▶ An active soft key is shown depressed and with yellow text

Folder List



Allows you to cut, copy, paste, rename, delete, and merge programs.

Will change the active window switching between Program List, Program Steps Preview, and Folder View.

Shows and hides the folder view (the figure to the right shows an active folder view window).

Returns you to the program edit mode.

- ▶ An arrow on a soft key indicates a list of options.
- ▶ Pressing the keypad number shown next to the option will activate that option.
- ▶ An inactive option is shown faded.
- ▶ An active soft key is shown depressed and with yellow text

Program Preview


Press the Change Window soft key to select the program preview window. When active, the background will turn white. The program preview allows you to preview a program without opening it for editing. With the program preview window active the following soft keys are available.

Change Window

The screenshot displays a CNC control interface with the following elements:

- Top Status Bar:** Stop Time: 0:05:28, Tool: 0.2500 Inch, Datum: 1, Scale: 1.0000, Skew: 0.0000*, Inch.
- File Browser:** USER:user\Exercises\ (39) Free: 19.3 GB. The left pane shows a tree view with folders: MILLPWR, USER, service, user, Exercises, and Recycle bin. The right pane lists files including Example Program G2..., EXERCISE 1.MPT, EXERCISE 1.PNG, EXERCISE 2.MPT, EXERCISE 2.PNG, EXERCISE 3.MPT, EXERCISE 3.PNG, EXERCISE 4.MPT, EXERCISE 4.PNG, EXERCISE 5 R8.MPT, EXERCISE 5.MPT, EXERCISE 5.PNG, EXERCISE 6 with isla..., EXERCISE 6.MPT, EXERCISE 6.PNG, EXERCISE 7.MPT, EXERCISE 7.PNG, EXERCISE 8 .MPT, EXERCISE 8 .PNG, EXERCISE 8 DXF.DXF, GEOCALC EXAMPLE..., and GEOCALC EXAMPLE....
- Parameter List:**
 - Size.Y = 2.000000
 - zBegin = 0.010000 ABS
 - Depth = -0.250000 ABS
 - zPass = 3
 - zFeed = 10.0
 - Corner_Radius = 0.125000
 - Direction = CCW
 - Feed_Rate = 10.0
 - Tilt_Angle = 0.0
 - Finish.Dir = CCW
- 3D Model:** A 3D rendering of a rectangular part with a central slot and four holes, shown in a perspective view.
- Bottom Status Bar:** Loaded Program: EXERCISE 1.MPT, Program Type: All files, 00:05:28.
- Soft Keys:** Top of Program, Page Up, Page Down, Page Left, Page Right, Change Window, Folder View, Exit.

Program Preview



Returns you to the top of the program.

Navigates up one page with each press.

Navigates down one page with each press.

Navigates left one page with each press.

Navigates right one page with each press.

Shows and hides the folder view (showing with program preview active in example).

Returns you to the program edit mode.

- ▶ An unavailable soft key is shown with dull yellow text.
- ▶ An available inactive soft key is shown with black text.
- ▶ An active soft key is shown depressed and with yellow text

Creating & Editing a Program

In programming mode you can assemble a sequence of events to machine a complex part. In addition to all the canned cycles previously mentioned, custom contours and pockets, engraving, comments can be entered for display at run time, and auxiliary functions can be triggered, and multiple tool changes programmed. All this is available at the control and easily programmed using information directly off of the print in hand.

The control also allows simple and advanced math calculation directly in any entry field using the keypad and the CALC key to access advanced calculator functions. The graphics provide you with a choice of 2D, 3D, and #d solid views and can be customized to suit your needs. The part graphics updates with every programmed step you create and also can be updated by pressing the decimal key.

For proofing your program Run Options allow you to run your program in graphics only, single step, and in dry run modes. You can skip a step by highlighting it and pressing the +/- key. Conversely, you can highlight any skipped step and press the +/- key to remove the skip designation. The feed rate override will also provide you with additional control throughout the process of confirming your program will run as expected.

The screenshot displays a CNC control interface. At the top, a status bar shows: Stop Time: 0:19:30, Tool: 0.5000 Inch, Datum: 1, Scale: 1.0000, Skew: 0.0000*, and Inch. Below this, the program name 'Pocketing.mpt' and '1 of 25' are shown. A 3D model of a milled part is visible on the right, featuring a central square pocket with four rounded corners and two smaller rectangular pockets. A blue tool tip is positioned above the central pocket. A coordinate system (YZX) is shown in the upper left of the 3D view.

The program editor on the left lists the following steps:

```

001 COMMENT
002 SET TOOL
003 CIRCLE POCKET
004 RECTANGLE POCKET
005 COMMENT
006 MILL LINE
007 MILL ARC
008 MILL LINE
009 MILL LINE
010 CUSTOM POCKET
011 COMMENT
012 SET TOOL
013 SLOT CONTOUR
014 SLOT CONTOUR
015 SLOT CONTOUR
016 SLOT CONTOUR
017 MILL LINE
018 MILL LINE
019 MILL LINE
020 MILL LINE
021 CUSTOM POCKET
  
```

At the bottom, a control panel contains the following buttons: Program Functions, Step Functions, Program Steps, Clear Program, Shutdown, Save/ Discard, and Run Options.

Creating & Editing a Program

Step Functions

The triangle in the lower right corner of a soft key indicates that pressing it will open another layer of soft keys. The Step Functions soft key accesses the soft keys listed below.

Step
Functions
—

Explode	Reverse Step	Reverse Path	Shift/Rotate Steps	Change Steps	Delete Steps	Copy/Move Steps
<p>Pressing the Explode soft key will explode a highlighted program step into individual steps allowing you to modify them individually and also begin or resume machining from a specific step. You can explode the following functions: Hole Patterns, Repeat, Mirror, and Rotate Steps.</p>	<p>Switches the FROM and TO points and TOOL OFFSET of a highlighted step. Place the highlight cursor on any step and press the softkey to reverse a step. The offset is reversed to keep the cutter compensation on the same side of the path when reversing direction.</p>	<p>Reverses any continuous tool path in the same manner as reverse step. Place the highlight cursor within any path and press the softkey to reverse a step.</p>				

- ▶ An unavailable soft key is shown with dull yellow text.
- ▶ An available inactive soft key is shown with black text.
- ▶ An active soft key is shown depressed and with yellow text.

Creating & Editing a Program

Step Functions

The triangle in the lower right corner of a soft key indicates that pressing it will open another layer of soft keys. The Step Functions soft key accesses the soft keys listed below.

Step
Functions
—

Explode		Reverse Step	Reverse Path	Shift/Rotate Steps	Change Steps	Delete Steps	Copy/Move Steps
---------	--	--------------	--------------	--------------------	--------------	--------------	-----------------

- ▶ An unavailable soft key is shown with dull yellow text.
- ▶ An available inactive soft key is shown with black text.
- ▶ An active soft key is shown depressed and with yellow text.

Pressing the Explode soft key will explode a highlighted program step into individual steps allowing you to modify them individually and also begin or resume machining from a specific step. You can explode the following functions: Hole Patterns, Repeat, Mirror, and Rotate Steps.

Shift Steps		
Step Range		
First	<input type="text"/>	
Last	<input type="text"/>	
Shift		
X	<input type="text"/>	Inc
Y	<input type="text"/>	Inc
Z	<input type="text"/>	Inc

Rotate Steps		
Step Range		
First	<input type="text"/>	
Last	<input type="text"/>	
Center		
X	<input type="text"/>	Abs
Y	<input type="text"/>	Abs
Angle		
	<input type="text"/>	

Creating & Editing a Program

Step Functions

The triangle in the lower right corner of a soft key indicates that pressing it will open another layer of soft keys. The Step Functions soft key accesses the soft keys listed below.

Step
Functions
—

Explode		Reverse Step	Reverse Path	Shift/Rotate Steps	Change Steps	Delete Steps	Copy/Move Steps
---------	--	--------------	--------------	--------------------	--------------	--------------	-----------------

- ▶ An unavailable soft key is shown with dull yellow text.
- ▶ An available inactive soft key is shown with black text.
- ▶ An active soft key is shown depressed and with yellow text.

Change Steps	
Step Range	
First	<input type="text"/>
Last	<input type="text"/>
Z	
Begin	<input type="text"/> Abs
End	<input type="text"/> Abs
Peck	<input type="text"/> Number
Pass	<input type="text"/> Number
	<input type="text"/>
Feed	<input type="text"/> IPM
Offset	
Offset	<input type="text"/>
Feed Rate	
Feed	<input type="text"/> IPM
Skip Steps	
	<input type="text"/>

Gives you the ability to change several steps simultaneously or mark them to be skipped. Enter the first and last step of the range you wish to change and define the changes to be made in the fields provided. You can change one or more of the variables using the fields provided. Steps that are set to be skipped will be shown greyed out with an asterisk. A skipped step cannot be edited. Once back to programming mode, highlighting a skipped step and pressing the +/- key will remove the skip tag. Conversely, you can highlight any step and press the +/- key to mark it to be skipped individually.

Creating & Editing a Program

Step Functions

The triangle in the lower right corner of a soft key indicates that pressing it will open another layer of soft keys. The Step Functions soft key accesses the soft keys listed below.

Step
Functions
—

Explode		Reverse Step	Reverse Path	Shift/Rotate Steps	Change Steps	Delete Steps	Copy/Move Steps
---------	--	--------------	--------------	--------------------	--------------	--------------	-----------------

- ▶ An unavailable soft key is shown with dull yellow text.
- ▶ An available inactive soft key is shown with black text.
- ▶ An active soft key is shown depressed and with yellow text.

Allows you to delete a range of steps you designate at the same time. The Clear key will delete a single highlighted step.


Makes it easy for you to duplicate or rearrange steps within your program. Place the cursor in the location you wish to copy or move to.

```
*Pocketing.mpt 2 of 25
001 *COMMENT
002
003 *CIRCLE POCKET
004 *RECTANGLE POCKET
005 *COMMENT
006 *MILL LINE
007 *MILL ARC
008 *MILL LINE
009 *MILL LINE
010 *CUSTOM POCKET
011 *COMMENT
012 SET TOOL
013 SET CONTOUR
```


Program Steps

Pressing Program Steps opens soft key features that include alternative access to Tool, Position / Milling, Hole Pattern, Rectangle, and Circle and are to the same hard key functions listed earlier. In addition the following program steps are available.

Program
Steps



Program Steps

Custom Pocket

Place the custom pocket step at the end of a continuous tool path.

Step Range

Will indicate the range of steps detected.

Staging Point (Optional)

Where the tool will rapid to above the pocket.

Z

- **Pass:** Establishes the number of cuts between the Z Begin and End.
- **Feed:** Establishes the Z rate of motion for the Z axis only.

Tool

Feed in the Tool field establishes the rate at which the tool will feed along the X, Y plane.

Finish

Establishes the amount of stock (Cut) to leave for the final finish pass along with the Feed rate and Direction to use.

Stepover

Allows you to define the percentage of the tool to use per pass for the roughing cut. The default is 50%.


Custom Pocket			
Step Range		Stepover	
First	<input type="text" value="17"/>	<input type="text" value="50"/>	%
Last	<input type="text" value="21"/>		
Staging Point			
X	<input type="text"/>	Abs	
Y	<input type="text"/>	Abs	
Z			
Pass	<input type="text" value="1"/>	Number	
Feed	<input type="text" value="10.0"/>	IPM	
Tool			
	<input type="text" value="0.1250"/>	Inch	
	<input type="text" value="FL END ML"/>	Type	
Feed	<input type="text" value="30.0"/>	IPM	
Finish			
Bottom	<input type="text" value="0.0000"/>		
Side	<input type="text" value="0.0200"/>		
Feed	<input type="text" value="10.0"/>	IPM	
Direction	<input type="text" value="CCW"/>		

Program Steps

Island

Added to a closed tool path, Island defines an area to remain uncut within a custom pocket. Lines and arcs used to describe an island must immediately precede the island step and the Island step must immediately precede the steps for the custom pocket contour followed by the Custom Pocket Step. Anything placed in-between will interrupt the cycle. Place the cursor beneath your irregular tool path, press the Program Steps soft key then the Custom Pocket soft key. Highlight Island and press enter or press the 8 key to add a contour step to an irregular tool path.


Program
Steps



Program Steps

Island

Circle and rectangle pocket cycles and slot cycles can be used as islands when set as contour within the step.



Using lines and arcs to create Islands.

Island

Step Range

First


Last

CustomPocket.mpt		5 of 19
001	SET TOOL	
002	MILL LINE	
003	MILL LINE	
004	MILL LINE	
005	ISLAND	
006	MILL LINE	
007	MILL LINE	
008	MILL LINE	
009	ISLAND	
010	MILL LINE	
011	MILL LINE	
012	MILL LINE	
013	ISLAND	
014	MILL LINE	
015	MILL LINE	
016	MILL LINE	
017	MILL LINE	
018	MILL LINE	
019	CUSTOM POCKET	

Program Steps

Island

Circle and rectangle pocket cycles and slot cycles can be used as islands when set as contour within the step.



Setting a canned cycle to Contour for use as an Island.

012	SET TOOL
013	<input checked="" type="checkbox"/> SLOT CONTOUR
014	<input type="checkbox"/> SLOT CONTOUR
015	<input type="checkbox"/> SLOT CONTOUR
016	<input type="checkbox"/> SLOT CONTOUR
017	<input type="checkbox"/> MILL LINE
018	<input type="checkbox"/> MILL LINE
019	<input type="checkbox"/> MILL LINE
020	<input type="checkbox"/> MILL LINE
021	<input type="checkbox"/> CUSTOM POCKET
022	<input type="checkbox"/> SET TOOL
023	<input type="checkbox"/> ROUGH MILL
024	<input type="checkbox"/> SET TOOL
025	<input type="checkbox"/> ROUGH MILL

Type	<input type="text" value="Contour"/>

Advanced Custom Pocket Machining Features

Contours are describes using Lines, Arcs, Blends, and Chamfers.

	*Pocketing.mpt	End of 19
	001 SET TOOL	
Canned cycles can be designated as contours and now used as Islands.	002 □ SLOT CONTOUR	All Islands must precede the contour of the custom pocket. Islands are allowed to overlap each other and overlap the custom pocket.
	003 □ SLOT CONTOUR	
Contours can define Islands when followed by the Island step.	004 □ SLOT CONTOUR	
	005 □ SLOT CONTOUR	
	006 ▮ MILL LINE	
Contours define custom pockets when followed by the custom pocket step.	007 ▮ MILL LINE	Advanced features must follow the custom pocket step.
	008 ▮ MILL LINE	
	009 ▮ MILL LINE	
	010 ▮ CUSTOM POCKET	
	011 SET TOOL	
Advanced pocketing features can be added to a custom pocket. And are indicated by the dashed contour line extension.	012 ▮ PILOT DRILL	If a tool change is needed the tool step must precede the advanced feature. If no tool step is added, the previous tool will be used.
	013 SET TOOL	Rough milling must precede finish milling.
	014 ▮ ROUGH MILL	
	015 SET TOOL	Bottom finish must precede side finish.
	016 ▮ ROUGH MILL	

Custom Pocket

Pilot Drill

(use if there is not room for a ramp in move)

The Pilot Drill option (Step 12) when used with a tool step (Step 11) will drill a pilot hole at every location where a tool needs to plunge. This allows you to use a tool that cannot center cut. The step will show you two tool fields. The first field is the preceding tool step and the second indicates the default tool (the tool that precedes this routine).

During operation a prompt is displayed to use the pilot tool. Holes are then drilled at each calculated entry location. These locations are calculated with each run so any program change is automatically accounted for. The tool retracts to the active datum's retract position between holes.

Peck

The distance between each chip break move.

Feed

The rate of downward Z-Axis feed.

Tool

Indicates the tool to be used when pilot drilling

Rough Tool

Indicates the tool that will be used for roughing.

```

*Pocketing.mpt 12 of 19
001 SET TOOL
002 □ SLOT CONTOUR
003 □ SLOT CONTOUR
004 □ SLOT CONTOUR
005 □ SLOT CONTOUR
006 | MILL LINE
007 | MILL LINE
008 | MILL LINE
009 | MILL LINE
010 | CUSTOM POCKET
011 SET TOOL
012 | PILOT DRILL
013 SET TOOL
014 ROUGH MILL
015 SET TOOL
016 ROUGH MILL
017 SET TOOL
018 | BOTTOM FINISH
019 SET TOOL
          
```

Line 12 - Pilot Drill Step will predrill at the locations where a tool will plunge. It updates these locations each time the program is edited.

Pilot Drill			
Z	Peck	<input type="text"/>	Number IPM
	Feed	<input type="text" value="10.0"/>	
Tool		<input type="text" value="0.1000"/>	Inch Type
		<input type="text"/>	
Rough Tool		<input type="text" value="0.5000"/>	Inch Type
		<input type="text"/>	

Custom Pocket

Rough Mill

(Clear a pocket with a large diameter roughing tool)

Used with a tool step (Step 13), Rough Mill (Step 14) allows you to clear a custom pocket using a large diameter tool and finish with the default tool or a finish tool specified later. You can have multiple rough tools programmed. Each tool should be smaller than the previous. G2 will use each subsequent roughing pass only within the areas left by the previous roughing cycle. The first rough cycle is indicated with the blue arrows.

Pass

The number of passes or the distance per pass until final depth is reached.

Feed


The rate of interpolation rate in the XY plane.

Tool

Indicates the tool to be used for this Rough Mill step.

Coarse Tool

Indicates the tool used in a prior Rough Mill step. Since this is the first rough mill step, no prior rough tool is listed.



Line 14 – 1st Rough Mill Step

Rough Mill		
Z	Pass	<input type="text" value="0"/> Number
	Feed	<input type="text" value="10.0"/> IPM
Tool	<input type="text" value="0.5000"/>	Inch
	<input type="text"/>	Type
	Feed	<input type="text" value="7.5"/> IPM
Coarse Tool		
<input type="text"/>	Inch	
<input type="text"/>	Type	
Fine Rough		
<input type="text" value="Contour"/>		

Custom Pocket

2nd Rough Mill

(Clear areas the larger rough cycle cannot reach (Optional))

Used with a tool step (Step 15), Rough Mill (Step 16) continues to rough clear the custom pocket in areas the first cycle could not reach. Each roughing tool should be smaller than the previous. The same tool used for the last roughing cycle will be used for finish cycles if no additional tool change step is programmed.

Pass

The number of passes or the distance per pass until final depth is reached.

Feed


The rate of interpolation rate in the XY plane.

Tool

Indicates the tool to be used for this Rough Mill step.

Coarse Tool

Indicates the tool used in a prior Rough Mill step.



Line 16 – 2nd Rough Mill Step

Rough Mill		
Z	Pass	<input type="text" value="2"/> Number
	Feed	<input type="text" value="10.0"/> IPM
Tool	<input type="text" value="0.1250"/>	Inch
	<input type="text"/>	Type
	Feed	<input type="text" value="3.5"/> IPM
Coarse Tool	<input type="text" value="0.5000"/>	Inch
	<input type="text"/>	Type
Fine Rough	<input type="text" value="Contour"/>	

Custom Pocket

Bottom Finish & Side Finish

Bottom Finish (Line 17) and Side Finish (Line 18) allow you to complete a custom pocket routine. You can program more than one side finish. Specify the amount to remain for the second side finish in the Side field. If you do not specify a tool along before the finish steps the operation will proceed with the last current tool. You can specify a tool for the bottom finish and one for each side finish step if you wish. In this example the same tool will be used for the final rough pass and both finish operations.

Z

Feed: The rate the tool will feed between the Z Begin and End established in the contour steps that define the custom pocket

Finish


- ▶ **Cut:** Allows you to leave stock for a second side finish.
- ▶ **Feed:** The rate of interpolation rate in the XY plane.
- ▶ **Direction:** Establishes a climb cut or conventional cut.

Tool

Indicates the tool to be used for the finish step.


Line 17 – Bottom Finish

Bottom Finish		
Z	Feed	<input type="text" value="10.0"/> IPM
Finish	Feed	<input type="text" value="10.0"/> IPM
	Direction	<input type="text" value="CCW"/>
Tool	<input type="text" value="0.1250"/>	Inch
	<input type="text"/>	Type



Line 18 – Side Finish

Side Finish		
Z	Feed	<input type="text" value="10.0"/> IPM
Finish	Side	<input type="text" value="0.0000"/>
	Feed	<input type="text" value="30.0"/> IPM
	Direction	<input type="text" value="CCW"/>
Tool	<input type="text" value="0.1250"/>	Inch
	<input type="text"/>	Type



Custom Pocket Review

A Custom Pocket can be very versatile ranging from a simply clearing a contour to a multi event process involving specialty tooling such as high helix finishing tools, tapered end mills, etc. The minimum requirement for a custom pocket is a closed path contour. Adding one or more islands allows you to clear an area around features.

The **Pilot Drill** option allows you to use tooling not designed to plunge cut when room to ramp in is too limited. This options automatically determines the proper hole locations required every time the program is run adjusting when tool diameters are changed and the programmed contour is revised.

Rough Mill allows the use of custom tools to quickly and efficiently rough out an area reducing cycle time and extending tool life. It eliminates the need to program separate cycles one for roughing and another for finishing, reducing the amount of program need and editing later when part revisions are required. More than one roughing cycle can be added to a custom pocket allowing even greater flexibility.

Bottom and Side Finish cycles allow for enhances finishing these cycles allow you to designate separate tools for bottom and side finishing. When not added to a custom pocket cycle, the default tool will perform both bottom and side finish cycles. Below are examples of custom pockets from the simplest to the complex.

Custom Pocket Review

```
001 SET TOOL
002 MILL ARC
003 MILL ARC
004 CUSTOM POCKET
```

Tool (Step 1) will rough and finish the pocket as programmed.

```
001 SET TOOL
002 MILL LINE
003 MILL LINE
004 MILL LINE
005 MILL LINE
006 ISLAND
007 MILL ARC
008 MILL ARC
009 CUSTOM POCKET
```

Tool (Step 1) will rough and finish the pocket as programmed. Leaving the Island.

```
001 SET TOOL
002 MILL LINE
003 MILL LINE
004 MILL LINE
005 MILL LINE
006 ISLAND
007 MILL ARC
008 MILL ARC
009 CUSTOM POCKET
010 SET TOOL
011 ROUGH MILL
```

Tool (Step 10) will rough and tool (Step 1) will finish the pocket as programmed. Leaving the Island.

```
001 SET TOOL
002 MILL LINE
003 MILL LINE
004 MILL LINE
005 MILL LINE
006 ISLAND
007 MILL ARC
008 MILL ARC
009 CUSTOM POCKET
010 SET TOOL
011 PILOT DRILL
012 SET TOOL
013 ROUGH MILL
```

Tool (Step 10) will pilot drill then tool (Step 12) will rough then tool (Step 1) will finish.

Custom Pocket Review

```

001 SET TOOL
002 MILL LINE
003 MILL LINE
004 MILL LINE
005 MILL LINE
006 ISLAND
007 MILL ARC
008 MILL ARC
009 CUSTOM POCKET
010 SET TOOL
011 PILOT DRILL
012 SET TOOL
013 ROUGH MILL
014 SET TOOL
015 BOTTOM FINISH
016 SIDE FINISH

```

Tool (Step 10) will pilot drill then tool (Step 12) will rough then tool (Step 14) will bottom and side finish.

```

001 SET TOOL
002 MILL LINE
003 MILL LINE
004 MILL LINE
005 MILL LINE
006 ISLAND
007 MILL ARC
008 MILL ARC
009 CUSTOM POCKET
010 SET TOOL
011 PILOT DRILL
012 SET TOOL
013 ROUGH MILL
014 SET TOOL
015 BOTTOM FINISH
016 SET TOOL
017 SIDE FINISH

```

Tool (Step 10) will pilot drill then (Step 12) will rough then (Step 14) will bottom finish and (Step 16) will side finish.

```

001 SET TOOL
002 MILL LINE
003 MILL LINE
004 MILL LINE
005 MILL LINE
006 ISLAND
007 MILL ARC
008 MILL ARC
009 CUSTOM POCKET
010 SET TOOL
011 PILOT DRILL
012 SET TOOL
013 ROUGH MILL
014 SET TOOL
015 ROUGH MILL
016 SET TOOL
017 BOTTOM FINISH
018 SIDE FINISH

```

Tool (Step 10) will pilot drill, (Step 12) will rough first, (Step 14) will rough second, (Step 16) will bottom finish and side finish.

```

001 SET TOOL
002 MILL LINE
003 MILL LINE
004 MILL LINE
005 MILL LINE
006 ISLAND
007 MILL ARC
008 MILL ARC
009 CUSTOM POCKET
010 SET TOOL
011 PILOT DRILL
012 SET TOOL
013 ROUGH MILL
014 SET TOOL
015 ROUGH MILL
016 SET TOOL
017 BOTTOM FINISH
018 SET TOOL
019 SIDE FINISH

```


Tool (Step 10) will pilot drill, (Step 12) will rough first, (Step 14) will rough second, (Step 16) will bottom finish and (Step 18) will side finish.

Program Steps

Contour

(Now located under Position/Milling)

When added to the end of a continuous tool path Contour provides you with the ability to add a lead on (approach), lead off (Departure) to the tool path. In addition, it also provides the ability to cut the contour in progressive passes and apply a finish pass like those found in canned cycles. Place the cursor beneath your tool path, press the Program Steps soft key then the Position/Milling soft key. Highlight Contour or press the 6 key to add a contour step to a custom tool path consisting of lines, arcs, blends, and bevels.



Step Range

Will indicate the range of steps detected.

Approach

Choose None, Straight, or Arc for the approach type and provide a distance off of the contour to use.

Departure

Choose None, Straight, or Arc for the departure type and provide a distance off of the contour to use. Choose none if you plan to finish in a reverse direction.

Pass

Establishes the number of cuts between the Z Begin and End.


Finish

Establishes the amount of stock (**Cut**) to leave for the final finish pass for **Bottom** and **Side** finishing along with the **Feed** rate and **Direction** to use.

Contour	
Step Range	
First	<input type="text" value="4"/>
Last	<input type="text" value="8"/>
Approach	
	<input type="text" value="Straight"/>
	<input type="text" value="0.7500"/> Distance
Departure	
	<input type="text" value="Arc"/>
	<input type="text" value="0.5000"/> Distance
Z	
Pass	<input type="text"/> Number
Finish	
Bottom	<input type="text"/>
Side	<input type="text" value="0.1000"/>
Feed	<input type="text" value="50.0"/> IPM
Direction	<input type="text" value="Forward"/>

Program Steps

Pressing Program Steps opens soft key features that include alternative access to Tool, Position / Milling, Hole Pattern, Rectangle, and Circle and are to the same hard key functions listed earlier. In addition Repeat, Rotate, and Mirror are available.



Repeat

Allows you to run a set of program steps in multiple locations and/or in increasing depths. A repeat can be placed anywhere in the program after the original steps being repeated. Designate the step range, the X, Y, and or Z offset, any pattern option if desired, and the number of repeats.

Repeat	
Step Range	
First	<input type="text"/>
Last	<input type="text"/>
Pattern	
	Linear <input type="text"/>
Offset	
X	Array
Y	Frame
Z	<input type="text"/>
Repeat	
<input type="text"/>	More

Rotate

Like repeat, rotate allows you to run a set of program steps in multiple locations around a common point and if required in increasing depths. A rotate must be at some point after the original steps. Designate the step range, X, Y center and any Z offset. Angle establishes the amount of rotation between the number of repeats.

Rotate	
Step Range	
First	<input type="text"/>
Last	<input type="text"/>
Center	
X	<input type="text"/> Abs
Y	<input type="text"/> Abs
Z Offset	
	<input type="text"/>
Angle	
	<input type="text"/>
Repeat	
<input type="text"/>	More

Mirror

Allows you to flip a step range on an axis. A mirror step must be at some point after the original steps. Designate the step range. The 1st Axis Point is the begin point and the 2nd Axis Point is the end point that defines the reflection line that like the spine of a book anchors the mirror reflection. A change in Y defines a vertical line creating a left or right hand mirror. A change in X defines a horizontal line mirroring above or below. A change in both axes defines a diagonal line allowing a mirrored image on a bias.

Mirror	
Step Range	
First	<input type="text"/>
Last	<input type="text"/>
1st Axis Point	
X1	<input type="text"/> Abs
Y1	<input type="text"/> Abs
2nd Axis Point	
X2	<input type="text"/> Abs
Y2	<input type="text"/> Abs
Z Offset	
	<input type="text"/>

Program Steps

Engrave Line

Text

Enter the text to be engraved. Letters numbers and symbols are allowed. The Alphanumeric Keyboard Soft key activates a keyboard to enter the text.

Lower Left Corner

Locates the text on your work piece. This can be cartesian or polar, absolute (ABS) or incremental (INC) from an external reference point.

Character Height

Establishes the size of the text.

Z

- ▶ **Begin** is where the tool will rapid to.
- ▶ From there it will feed at the given rate to the **End** value at the **Feed** provided.
- ▶ This feed is for the Z axis only.
- ▶ When finished, the tool then rapids up to the retract plane set in datum.

Style


Select font style Simple, Stick, or Stencil.

Modifier


Select Normal or Mirrored.

Tool

Feed is the rate of feed in the X, Y plane.



Engrave Line		
Text		
<input type="text"/>		
Lower Left Corner		
X	<input type="text"/>	Abs
Y	<input type="text"/>	Abs
Character Height		
<input type="text"/>		
Angle		
<input type="text"/>		0.0000
Z		
Begin	<input type="text"/>	0.0100 Abs
End	<input type="text"/>	-0.2600 Abs
Feed	<input type="text"/>	10.0 IPM




A USB mouse and keyboard can be used for easy programming.

Program Steps

Engrave Arc

Text

Enter the text to be engraved. Letters numbers and symbols are allowed. The Alphanumeric Keyboard Soft key activates a keyboard to enter the text.



Center

Locates the text on your work piece. This can be cartesian or polar, absolute (ABS) or incremental (INC) from an external reference point.

Character Height

Establishes the size of the text.

Radius

Up or Down establisher the arc that the text follows.

Z

- ▶ **Begin** is where the tool will rapid to.
- ▶ From there it will feed at the given rate to the **End** value at the **Feed** provided.
- ▶ This feed is for the Z axis only.
- ▶ When finished, the tool then rapids up to the retract plane set in datum.

Style

Select Simple Stick or Stencil.

Modifier

Select Normal or Mirrored.

Tool

Feed is the rate of feed in the X, Y plane.

Engrave Arc		
Text	Z	
<input type="text"/>	Begin	0.0100 Abs
	End	-0.2600 Abs
	Feed	10.0 IPM
Center	Tool	
		0.2500 Inch
	FL END ML	Type
X <input type="text"/>	Abs	Feed
Y <input type="text"/>	Abs	10.0 IPM
Character Height		
<input type="text"/>		
Radius		
<input type="text"/>		Up
Angle		
<input type="text"/>		
Style		
Font	Simple ▼	
Modifier	Normal ▼	

B B B

Font Options

Program Steps

Comment

Allows you to keep setup notes, and prompt operators with specific instructions.

Message

The text you wish to keep as a reminder or prompt during program execution.


Display User Prompt

- ▶ When set to NO is skipped over during program execution.
- ▶ When set to YES, the message appears during program execution when the comment step is reached. The control then pauses until GO is pressed to resume program execution.



Comment	
Message	<input type="text" value="Type your Comment HERE"/>
Display User Prompt	<input type="text" value="Yes"/>

Alphanumeric
Keyboard



Program Steps

Auxiliary Function

When the optional Auxiliary Machine Interface (AMI) is connected to your MILLPWRG2, there are two coolant outputs and four auxiliary outputs available.

Coolant

Allows you to choose Off, Flood, or Mist. Coolant selection does not pause the program. Coolant is shut off upon the end of a program automatically.

Auxiliary Outputs



Allows you to signal one or more auxiliary devices such as an indexing table or other equipment. The output can be set to off, on, and pulsed for a specified time.

Display User Prompt

- ▶ Provides additional control by establishing timing sequences for the output activation.
- ▶ **No:** User prompt allows the output to turn on, off, or pulse without a pause or additional input. It is best when only coolant is being activated.
- ▶ **Before Step:** Causes the control to pause and prompt the operator to press GO. When GO is pressed, the functions execute as programmed.
- ▶ **After Step:** Will first execute the commanded functions then pause for a GO signal. The GO button, the remote stop go button, or a signal on the remote GO input of the AMI will tell G2 to resume. A programmable indexer connected to the remote go input can signal G2 to resume after it performs its operation.

Set Continuous

Tells G2 to perform this auxiliary function command without retracting or pausing the program, allowing you to turn on and off outputs 1 through 4 while machining within a contour.



Auxiliary Function	
Coolant	Off
Auxiliary Outputs	
Aux 1	Off
Aux 2	Off
Aux 3	Off
Aux 4	Off
Display User Prompt	
	No
Set Continuous	
	No

Program Steps

Dwell

Allows you to program a pause in the program for as little as 0.1 seconds. A Dwell of 0 will cause the program to Pause until the operator presses GO. This dwell being independent of other cycles will occur at the programmed retract plane.



Dwell		
Dwell	Time <input type="text"/>	Sec

Reference Point

Can be used to graphically indicate center points, tangent points and other features. They can also be used as an external reference when programming incrementally. By programming several items incrementally from a reference point, the features can be relocated later as needed by simply changing the reference point position. A reference point in a continuous tool path will break the path, otherwise, reference points do not cause a pause in your program.



Reference Point		
Point	X <input type="text" value="5.0000"/>	Abs
	Y <input type="text" value="5.0000"/>	Abs
Z	End <input type="text" value="0.0000"/>	Abs

- ▶ **X Y:** Define the location of the reference point. This can be cartesian or polar, absolute (ABS) or incremental (INC) from an external reference point.
- ▶ **Z:** End is an offset from Z datum from which you can increment Z depth using incremental with an external reference.

The Position Drill example to the right shows X incrementing 2.2500" from step 12 and 0.0000" incrementally in Y, while Z is programmed to increment -0.7500" inches from the Z end of step 12. Any step containing X, Y, and Z values including a reference point can be used as an external reference when using incremental programming. Reference points can work like an alternate datum.

Position / Drill			
Point	X <input type="text" value="2.2500"/>	Inc	<input type="text" value="10"/>
	Y <input type="text" value="0.0000"/>	Inc	<input type="text" value="10"/>
Z	Begin <input type="text" value="0.0100"/>	Abs	
	End <input type="text" value="-0.7500"/>	Inc	<input type="text" value="10"/>
	Peck <input type="text"/>	Number	
	Drill <input type="text"/>		
Feed	<input type="text" value="10.0"/>	IPM	


Sample Program

The following exercise will familiarize you with creating a program. A step by step explanation will guide you through programming the tools and the drilling and milling functions. The basic principals described here apply to all of the program functions in MILLPWR^{G2}.

Locating a Datum

The datum you choose may be a location indicated on the print or a location you choose as a matter of convenience. Choose a location where the majority of the dimensions refer. This will streamline data entry and reduce the amount of calculations needed. Although there is no datum identified on this print, you can see that the center of the part will simplify programming for the majority of the steps. Therefore we will use the center of the part as datum. This program could also be programmed from datum such as the upper left corner, the choice is yours to consider. Another consideration with every program is the order of operation. In this example we will pilot drill all holes, drill the through holes, then counter bore.

With the proper fixture plate (right), we can then place screws in two or three holes to hold down the part allowing the outer profile and inner bore to be machined without having to move clamps.



Sample Program

**DRO
PGM**



From the DRO press the DRO/PGM key to open the programming screen. Be sure INCH is displayed at the top of the screen before you begin programming.

The first step for this program is to establish the tool. We will use a #3 pilot drill.

To choose a tool already entered in your tool library, simply enter the number in the Tool Number field and press USE. For this tool we will enter the diameter and type only. The length is unknown at this time and not necessary. We will establish Z-Zero when the tool is mounted and ready to drill.





- ▶ Press the TOOL key.
- ▶ Enter the diameter of the drill 0.250".
- ▶ Arrow down to the tool type and press enter.
- ▶ Select Pilot Drill and press USE.




Set Tool	
Tool Number	<input type="text"/>
Size	
Diameter	<input type="text" value="0.2500"/> Inch
Length	<input type="text"/>
Plunge / Ramp	
Angle	<input type="text"/>
Tool Type	<input type="text" value="Pilot Drill"/>
Spindle	<input type="text" value="Off"/>
Speed	<input type="text"/> RPM
Tool Position	
X To	<input type="text"/> Abs
Y To	<input type="text"/> Abs
Z To	<input type="text"/> Abs
Require Change	<input type="text" value="No"/>

The four outer holes can be described as a rectangle frame pattern.




- ▶ Press HOLES then arrow down to Rectangle Frame or press 8.
- ▶ Enter 2.02 for the 1st Corner X1 location then arrow down or press ENTER and enter 2.02 for the Y1 location.
- ▶ Arrow down to Size and enter -4.04 for X and Y. Use negative values because the pattern falls to the left and below the first corner.
- ▶ We will establish the top of the part as Z zero so arrow down to Z Begin and enter .01.
- ▶ Arrow down to Z End and enter -.14. We will use the feed rate of 10.
- ▶ No pecking is required so leave this blank.
- ▶ Arrow down to Holes and enter 2 for both X and Y. You will notice the 2nd corner, Hole Spacing, and Center have been calculated and shown in blue.

Hole Frame					
1st Corner			Hole Spacing		
X1	2.0200	Abs	X	-4.0400	Between
Y1	2.0200	Abs	Y	-4.0400	Between
Size			Center		
X	-4.0400		X	0.0000	Abs
Y	-4.0400		Y	0.0000	Abs
2nd Corner			Angle		
X2	-2.0200	Abs	0.0000		
Y2	-2.0200	Abs	Tool Retract		
Z			Number		
Begin	0.0100	Abs	Dwell		Sec
End	-0.1400	Abs	Tool		
Peck		Number	0.2500		
Drill			PILOT DRL		
Feed	10.0	IPM	Tool		
Holes			Dwell		
X	2		Sec		
Y	2				




The four outer holes will appear in the graphics and the block form will adjust to fit.


The next step is to program the first of the two hole patterns that can be described as a bolt hole circle.



- ▶ Press HOLES then arrow down to Bolt Circle or press 4.
- ▶ The center location is at X and Y Zero and the Z begin and End have carried over from the previous step.
- ▶ Arrow down to the radius.
- ▶ Enter 1.625 for the radius.
- ▶ Since this is a full circle the direction is not important.
- ▶ Arrow down to Holes and enter 4.
- ▶ Arrow down to the Start angle and enter 45. The end angle is automatically calculated.
- ▶ Press USE.




The first set of four holes will appear in the graphics.



4X Ø .343 THRU Ø .68 -.00 +.03 X
82° CSK EQUALLY SPACED ON A
3.25" BOLT CIRCLE
2 PLACES



Bolt Circle	
Center	End Angle
X <input type="text" value="0.0000"/> Abs	<input type="text" value="315.0000"/>
Y <input type="text" value="0.0000"/> Abs	Tool Retract
Z	<input type="text"/> Number
Begin <input type="text" value="0.0100"/> Abs	Dwell <input type="text"/> Sec
End <input type="text" value="-0.1400"/> Abs	Tool
Peck <input type="text"/> Number	<input type="text" value="0.2500"/> Inch
Drill <input type="text" value="Drill"/> ▼	<input type="text" value="PILOT DRL"/> Type
Feed <input type="text" value="10.0"/> IPM	Tool
Radius	Dwell <input type="text"/> Sec
<input type="text" value="1.6250"/>	
Direction	
<input type="text" value="CCW"/> ▼	
Holes	
<input type="text" value="4"/>	
Start Angle	
<input type="text" value="45.0000"/>	

The next step is to program the second set of the two hole patterns that can be described as a bolt hole circle.



- ▶ Press HOLES then arrow down to Bolt Circle or press 4.
- ▶ All of the previous entries are carried forward.
- ▶ Arrow down to the Start angle and enter 70. The end angle is automatically calculated.
- ▶ Press USE.

The second bolt hole pattern will appear in the graphics.




4X Ø .343 THRU Ø .68 $-.00 +.03$ X
82° CSK EQUALLY SPACED ON A
3.25" BOLT CIRCLE
2 PLACES

Bolt Circle			
Center		End Angle	
X	<input type="text" value="0.0000"/> Abs	<input type="text" value="340.0000"/>	
Y	<input type="text" value="0.0000"/> Abs	Tool Retract	
Z		<input type="text"/>	Number
Begin	<input type="text" value="0.0100"/> Abs	Dwell	<input type="text"/>
End	<input type="text" value="-0.1400"/> Abs	Tool	
Peck	<input type="text"/> Number	<input type="text" value="0.2500"/> Inch	Type
	<input type="text" value="Drill"/>	<input type="text" value="PILOT DRL"/>	
Feed	<input type="text" value="10.0"/> IPM	Tool	
Radius	<input type="text" value="1.6250"/>	Dwell	<input type="text"/> Sec
Direction	<input type="text" value="CCW"/>		
Holes	<input type="text" value="4"/>		
Start Angle	<input type="text" value="70.0000"/>		

The next step is to change the tool to a letter V drill (0.377") and program the frame set of holes.



- ▶ Press the TOOL key.
- ▶ Enter the diameter of the drill 0.377".
- ▶ Arrow down to the tool type and press enter.
- ▶ Select Drill and press USE.
- ▶ Press HOLES then arrow down to Rectangle Frame or press 8.
- ▶ All of the previous entries from the first frame of holes are carried forward.
- ▶ Arrow down to the Z End and change it to -0.400" to insure you drill through.
- ▶ Press USE.



Set Tool	
Tool Number	<input type="text"/>
Size	
Diameter	<input type="text" value="0.3770"/> Inch
Length	<input type="text"/>
Plunge / Ramp	
Angle	<input type="text"/>
Tool Type	<input type="text" value="Drill"/>

Hole Frame			
1st Corner		Hole Spacing	
X1	<input type="text" value="2.0200"/> Abs	X	<input type="text" value="-4.0400"/> Between
Y1	<input type="text" value="2.0200"/> Abs	Y	<input type="text" value="-4.0400"/> Between
Size		Center	
X	<input type="text" value="-4.0400"/>	X	<input type="text" value="0.0000"/> Abs
Y	<input type="text" value="-4.0400"/>	Y	<input type="text" value="0.0000"/> Abs
2nd Corner		Angle	
X2	<input type="text" value="-2.0200"/> Abs	<input type="text" value="0.0000"/>	
Y2	<input type="text" value="-2.0200"/> Abs	Tool Retract	
Z		Number	
Begin	<input type="text" value="0.0100"/> Abs	<input type="text"/>	
End	<input type="text" value="-0.4000"/> Abs	Dwell <input type="text"/>	
Peck	<input type="text"/> Number	Tool	
Drill <input type="text" value="Drill"/>		<input type="text" value="0.3770"/> Inch	
Feed	<input type="text" value="10.0"/> IPM	<input type="text" value="DRILL"/> Type	
Holes		Tool	
X	<input type="text" value="2"/>	Dwell <input type="text"/> Sec	

The second frame of holes will appear in the graphics.


The next step is to change the tool to an 11/32" drill and program the two bolt hole patterns.



- ▶ Press the TOOL key.
- ▶ Enter the diameter of the drill 0.343".
- ▶ Arrow down to the tool type and press enter. Select Drill and press USE.




- ▶ Press HOLES then arrow down to Bolt Circle or press 4.
- ▶ The previous entries from the Bolt Circle step are carried forward along with the last Z depth used.
- ▶ Arrow down to the Start Angle and enter 45. The end angle is automatically calculated.
- ▶ Press USE.
- ▶ Create another hole pattern with a 70 degree start angle.



Center		
X	<input type="text" value="0.0000"/>	Abs
Y	<input type="text" value="0.0000"/>	Abs
Z		
Begin	<input type="text" value="0.0100"/>	Abs
End	<input type="text" value="-0.4000"/>	Abs
Peck	<input type="text"/>	Number
	<input type="text" value="Drill"/>	
Feed	<input type="text" value="10.0"/>	IPM
Radius		
	<input type="text" value="1.6250"/>	
Direction		
	<input type="text" value="CCW"/>	
Holes		
	<input type="text" value="4"/>	
Start Angle		
	<input type="text" value="45.0000"/>	

Center		
X	<input type="text" value="0.0000"/>	Abs
Y	<input type="text" value="0.0000"/>	Abs
Z		
Begin	<input type="text" value="0.0100"/>	Abs
End	<input type="text" value="-0.4000"/>	Abs
Peck	<input type="text"/>	Number
	<input type="text" value="Drill"/>	
Feed	<input type="text" value="10.0"/>	IPM
Radius		
	<input type="text" value="1.6250"/>	
Direction		
	<input type="text" value="CCW"/>	
Holes		
	<input type="text" value="4"/>	
Start Angle		
	<input type="text" value="70.0000"/>	

The two bolt hole patterns will appear in the graphics.




The next step is to change the tool to a counter sink drill and program the two bolt hole patterns again.



- ▶ Press the TOOL key.
- ▶ Enter a diameter of 0.680".
- ▶ Arrow down to the tool type and press enter. Select Counter-Sink and press USE.



- ▶ Press HOLES then arrow down to Bolt Circle or press 4.
- ▶ The previous entries from the bolt Circle step are carried forward along with the last Z depth used.
- ▶ Arrow down to the Z Depth and change it to -0.204".
- ▶ Arrow down to the Start Angle and enter 45.
- ▶ Press USE.
- ▶ Create another hole pattern with a 70 degree start angle.





Center		
X	<input type="text" value="0.0000"/>	Abs
Y	<input type="text" value="0.0000"/>	Abs
Z		
Begin	<input type="text" value="0.0100"/>	Abs
End	<input type="text" value="-0.2040"/>	Abs
Peck	<input type="text"/>	Number
	<input type="text" value="Drill"/>	
Feed	<input type="text" value="10.0"/>	IPM
Radius		
	<input type="text" value="1.6250"/>	
Direction		
	<input type="text" value="CCW"/>	
Holes		
	<input type="text" value="4"/>	
Start Angle		
	<input type="text" value="45.0000"/>	

Center		
X	<input type="text" value="0.0000"/>	Abs
Y	<input type="text" value="0.0000"/>	Abs
Z		
Begin	<input type="text" value="0.0100"/>	Abs
End	<input type="text" value="-0.2040"/>	Abs
Peck	<input type="text"/>	Number
	<input type="text" value="Drill"/>	
Feed	<input type="text" value="10.0"/>	IPM
Radius		
	<input type="text" value="1.6250"/>	
Direction		
	<input type="text" value="CCW"/>	
Holes		
	<input type="text" value="4"/>	
Start Angle		
	<input type="text" value="70.0000"/>	

With the holes completed two or more bolts can be used to hold the work piece by screwing them down in tapped holes strategically placed in the fixture below. Now the center hole and outer profile can be machined without interference from clamps.



- ▶ Press the TOOL key.
- ▶ Enter a diameter of 0.500".
- ▶ Arrow down to the tool type and press enter.
- ▶ Select Flat Endmill and press USE.
- ▶ Press CIRCLE then press enter for pocket.
- ▶ The previous entries from the Bolt Circle step are carried forward along with the last Z depth used.
- ▶ Arrow down to the Z Depth and change it to -0.260".
- ▶ Arrow down to Pass and enter 2.
- ▶ Arrow down to radius and enter 1.2525
- ▶ Press USE.




Circle			
Center		Finish	
X	<input type="text" value="0.0000"/>	Abs	Bottom <input type="text" value="0.0000"/>
Y	<input type="text" value="0.0000"/>	Abs	Side <input type="text" value="0.0000"/>
Z		Feed <input type="text" value="0.0"/> IPM	
Begin	<input type="text" value="0.0100"/>	Abs	Direction <input type="text" value="CCW"/>
End	<input type="text" value="-0.2600"/>	Abs	Stepover
Pass	<input type="text" value="2"/>	Number	
Feed	<input type="text" value="10.0"/>	IPM	Type
Radius		<input type="text" value="Pocket"/>	
Direction		<input type="text" value="CCW"/>	
Tool		Feed <input type="text" value="10.0"/> IPM	
<input type="text" value="0.5000"/>		Inch	
<input type="text" value="FL END ML"/>		Type	

Rectangle Frame is the best option for the outer profile. Because the print clearly indicates the size of the rectangle and because we established Datum as the center we will use this information to program this frame. This outer profile could also be described using lines to describe the shape. If you are, for example, converting a DXF file then this would be the best solution.



- ▶ Press the Rectangle key.
- ▶ Choose Frame from the list by highlighting Frame and pressing Enter or by pressing the 8 key.
- ▶ Arrow down to the size and enter 5 for both X and Y.
- ▶ Review the Z information and insure it is the same as the previous circle pocket.
- ▶ Arrow down to Corner and select Chamfer and enter 0.25.
- ▶ Arrow down to Offset and select Outside.
- ▶ Arrow down to Center and enter zero for both X and Y.
- ▶ Press USE.

Rectangle Frame			
1st Corner		Tool	
X1	<input type="text" value="-2.5000"/>	Abs	<input type="text" value="0.5000"/> Inch
Y1	<input type="text" value="-2.5000"/>	Abs	<input type="text" value="FL END ML"/> Type
Size		Offset	<input type="text" value="Outside"/>
X	<input type="text" value="5.0000"/>	Feed	<input type="text" value="10.0"/> IPM
Y	<input type="text" value="5.0000"/>	Center	
2nd Corner		X	<input type="text" value="0.0000"/> Abs
X2	<input type="text" value="2.5000"/> Abs	Y	<input type="text" value="0.0000"/> Abs
Y2	<input type="text" value="2.5000"/> Abs	Angle	
Z		<input type="text" value="0.0000"/>	
Begin	<input type="text" value="0.0100"/> Abs	Finish	
End	<input type="text" value="-0.2600"/> Abs	<input type="text" value="0.0000"/> Cut	
Pass	<input type="text" value="2"/> Number	Feed	<input type="text" value="0.0"/> IPM
Feed	<input type="text" value="10.0"/> IPM	Direction	<input type="text" value="CCW"/>
Corner			
Chamfer	<input type="text" value="0.2500"/> Length		
Direction			
		<input type="text" value="CCW"/>	



The graphics will show a complete part and the block form for the graphics automatically sizes to include maximum depth, width, and length of the program. You can adjust the block form if you wish to better represent the stock size of your work piece.

VIEW


Block Form

- ▶ Press the view Key then press the Block Form Soft Key. The form opens and you will find all the values are blue indicating calculated values.
- ▶ Enter the values that best describe the stock you will be using.
- ▶ Press USE.
- ▶ Press Cancel to exit view mode.


Calculated values are blue while entered values are black. Calculated values are best while you build your program because the view will automatically scale down as you add steps. You can have a mix of calculated and entered values.

Connecting a mouse to one of the USB ports allows you to left click and drag in the graphics to rotate the part and right click and drag to pan.

Block Form	
X Axis	
Min	-3.6000
Max	3.6000
Y Axis	
Min	-3.6000
Max	3.6000
Z Axis	
Min	-0.4820
Max	0.0100
User Values	
Enabled	No



Block Form	
X Axis	
Min	-2.5000
Max	2.5000
Y Axis	
Min	-2.5000
Max	2.5000
Z Axis	
Min	-0.2500
Max	0.0000
User Values	
Enabled	No



The program is now complete. At this point it is a good idea to save the program. An estimated run time is calculated in the top status bar. This does not include time for tool changes. It is highly recommended that you verify the program prior to cutting. You can preview the cutting operation graphically by selecting Graphics Only found under the Run Options soft key.

Program
Functions

Save/
Discard

7 Save

8 Discard

Save/
Discard

To save your work

- ▶ Press the Program Functions soft key.
- ▶ Press the Save / Discard soft key.
- ▶ Press Enter to save the program.
- ▶ Name the program "Example Program G2" and press USE.

Run
Options

GO

To proof the program

- ▶ Press the Run Options soft key and select Dry Run and Graphics Only.
- ▶ Insure you are on step 1 and press GO. When you are satisfied with your program insure Dry Run and Graphics Only are off and begin first piece machining.

Run
Options

Graphics
Only



Geometry Calculator

The geometry calculator's layout is similar to the program mode except the step list is on the right and the graphic window is on the left. This calculator is capable of creating points, lines, and arcs, relative to features you select. The capabilities provided here can allow you to program features when very little dimensional data is known. The sample program we will use is challenging to the most seasoned programmer. You will see that with the Geometry Calculator a challenge such as this is easily overcome.

CALC


Geometry

Calc
Functions

Access the Geometry Calculator by pressing the CALC key, then the Geometry soft key when in the program edit screen. It is not accessible from the DRO.


Once in the geometry calculator you can press the Calc Functions key or simply begin creating geometry. When you press the Calc Functions soft key you can use the following functions:

- ▶ **Clear Calculator:** Clears any geometry currently entered and displayed.
- ▶ **Save Calculator:** Saves your work allowing you to reload it if cleared.
- ▶ **Load Calculator:** Loads any saved items from above.
- ▶ **Load Program:** Loads your current program converting it to geometric steps. This saves time since you do not have to reenter work you already accomplished.



You can select these options using the arrow keys and enter key or press the corresponding number on the keypad that is displayed to the right of each option.


The geometry calculator uses positions, lines, and arcs as building blocks. With one or two of these items selected, you can then find additional positions, lines, and arcs relative to those selected. Once found, they can be returned to your program. If you entered the geometry calculator while in a from, to, center, or third point in program step, you can return a position directly into this step. If you enter the geometry calculator without being in an open program step, you can return a position as a drill position or return an entire line or arc to be used as part of a tool path.




To create a position called a GeoPoint:

- ▶ Press the yellow POS key.
- ▶ A window will open asking for the X and Y coordinates. Z Axis data is not taken into consideration in the calculator. The Z Axis information, offsets, and feeds will be carried forward from the previous step as you return information to your program.
- ▶ Teach position allows you to transfer the current machine position to the GeoPoint and Polar allows you to define the position using a radius and angle from Datum zero.
- ▶ Enter the X and Y coordinates and press USE to complete.

GEOPOINT		
Point		
X	<input type="text" value="1.0000"/>	Abs
Y	<input type="text" value="1.0000"/>	Abs






To create a GeoLine:

- ▶ Press the yellow Line key. Enter the information you have to define the line. It can be defined the same as a line when programming.
- ▶ **From:** X1 Y1 define the start point of the line. These can be cartesian or polar, absolute only.
- ▶ **To:** X2 Y2 is the end of the line and can be cartesian or polar, absolute only.
- ▶ **Angle:** Allows you to create a line by programming to an X or a Y value at this given angle. As you can see to the right, the X2 value has been calculated and appears in blue. By striking a line from X 2.0, Y 2.0 at 20° until Y 3.0 is reached we calculate the X2 value to be 3.7321.


GEOLINE			
From			
X1	<input type="text" value="2.0000"/>	Abs	
Y1	<input type="text" value="2.0000"/>	Abs	
To			
X2	<input type="text" value="4.0000"/>	Abs	
Y2	<input type="text" value="3.0000"/>	Abs	
Angle			
	<input type="text" value="26.5651"/>		

Teach Position	Polar
-------------------	-------



In each of these four examples, the unknown coordinate “???” when left blank will be calculated based on the angle provided.

The ARC key opens the arc dialogue allowing you to define an arc. In the Geometry Calculator, an arc can be programmed using only the center, radius, and direction. This is very useful when your intent is to determine tangent points.








- ▶ **From:** X1 Y1 define the start point of the arc. These can be cartesian or polar, absolute only.
- ▶ **To:** X2 Y2 is the end of the arc and can be cartesian or polar, absolute only.
- ▶ **Radius:** Establishes the size of the arc. Minor or Major can be established. Minor arcs are less than 180 degrees while Major arcs are greater than 180 degrees.
- ▶ **Direction:** Establishes clockwise (CW) or counter clockwise (CCW) direction.
- ▶ **Center:** Allows you to define the center point of an arc. This is useful if a radius is not defined on your print. Do not enter a radius prior to entering the center point.
- ▶ **3rd Point:** Provides you with yes another method of defining an arc. By programming a from, to, and third point, an arc can be determined. The third point does not have to be within the From and To points.
- ▶ **Sweep Angle:** An alternative entry for when the from or to point is unknown. If a from point is entered with a radius and a sweep angle, the To point can be calculated.


GEOARC		
From	X1	Abs
	Y1	Abs
To	X2	Abs
	Y2	Abs
Radius		Major
Direction		
Center	X	Abs
	Y	Abs
3rd Point	X3	Abs
	Y3	Abs
Sweep Angle		

Teach Position	Polar
----------------	-------

Ways to program an arc



After you create geometry or load your program into the calculator you can easily find relative features by selecting one or two items, then pressing the Find Point, Find Line, or Find Arc soft keys.




The chart to the right illustrates the possibilities depending on the combination of items selected. (A larger version appears on the next page.)

Select Feature

To select an item, highlight the item and press the Select Feature soft key. When selected, an arrow will appear beside the item as shown below. To deselect an item, highlight it again and press the Select Feature soft key. The arrow will disappear indicating the item is no longer selected. Because only one or two items can be selected at a time, when you select a third item, the first item will automatically become deselected. As you become familiar with this calculator this feature will become a great time saver.

Return Feature


























The Return Feature soft key will return a highlighted feature to your program. If you entered the calculator while within a program step, the coordinate pertinent to the step is transferred. If you entered the calculator between two program steps or at the end of your program, the entire item will transfer as a separate program step.



MILLPWR^{G2} Geometry Calculator Find Item Chart

Items Selected	Find Point	Find Line	Find Arc	No Radius Entered
2 Points 	 Midpoint between the given points	 Line between the given points	 Given a radius, all arcs through the given points	 Two arcs, each tangent to both points with the midpoint as its center point.
1 Point 1 Line 	 A point which, with the given point, would form a line perpendicular to the given line	 Lines through the point one parallel and one perpendicular to the given line	 Given a radius, all arcs through the given point and tangent to the given line	 Two arcs, each tangent to the given line with the given point as its center point.
1 Point 1 Arc 	 Points which, with the given point, would form lines tangent to the arc, and the shortest line between the point and the arc	 Lines through the given point tangent to the given arc, and the shortest line through the given point to the given arc	 Given a radius, all arcs through the given point and tangent to the given arc	 Arc tangent to the given arc with the given point as its center point.
2 Lines 	 Intersection point of the given lines	 Line that bisects the angle formed where the given lines intersect; line perpendicular to the bisector	 Given a radius, all arcs tangent to both given lines	
1 Line 1 Arc 	 Points where given line intersects the given arc	 Lines perpendicular to the given line, tangent to the given arc; shortest line to the given arc; perpendicular to the given line	 Given a radius, all arcs tangent to the given line and the given arc	
2 Arcs 	 Intersection points	 Lines tangent to arcs; shortest line between arcs	 Given a radius, all arcs tangent to both arcs	No Angle Entered
1 Arc 	 Center point, endpoints	 Given an angle, all lines tangent to and through the center point of the arc	 The complimentary Arc is found.	 With no angle, lines from the end points to the center point
1 Line 	 End points of the given line	 Given a distance, lines parallel and perpendicular to the given line through its end points	<p>Items in black are examples of the selected items indicated to the left.</p> <p>Items in red represent the results from pressing the find item key indicated at the top of the column.</p>	

MILLPWR⁵² Geometry Calculator Find Item Chart

Items Selected	Find Point	Find Line	Find Arc	No Radius Entered
2 Points X	X X Midpoint between the given points	X Line between the given points		 Two arcs, each tangent to both points with the mid-point as its center point.
1 Point 1 Line X	 A point which, with the given point, would form a line perpendicular to the given line	 Lines through the point, one parallel and one perpendicular to the given line		 Two arcs, each tangent to the given line with the given point as its center point.
1 Point 1 Arc X	 Points which, with the given point, would form lines tangent to the arc, and the shortest line between the point and the arc	 Lines through the given point tangent to the given arc, and the shortest line through the given point to the given arc		 Arcs tangent to the given arc with the given point as its center point.
2 Lines	 Intersection point of the given lines	 Line that bisects the angle formed where the given lines intersect; line perpendicular to the bisector		
1 Line 1 Arc	 Points where given line intersects the given arc	 Lines perpendicular to the given line, tangent to the given arc; shortest line to the given line, perpendicular to the given line		
2 Arcs	 Intersection points	 Lines tangent to arcs; shortest line between arcs		
1 Arc	 Center point, end points	 Given an angle, all lines tangent to arc through the center point of the arc.		 The complimentary Arc is found.
1 Line	 End points of the given line	 Given a distance, lines parallel and perpendicular to the given line through its end points		

Items in black are examples of the selected items indicated to the left. Items in red represent the results from pressing the find item key indicated at the top of the column.

No Angle Entered

With no angle, lines from the end points to the center point.

Geometry Calculator Example Program


This programming example (below right) would be a challenge on any CNC platform. We will use the Geometry Calculator like you would use a compass and square to easily tackle this challenge. Begin this exercise from the program editing mode.

Begin at the left end of the bottom line and proceed around the part in a counterclockwise direction.

Stop	Time: 0:00:28	Tool: 0.5000 Inch	Datum: 1	Scale: 1.0000	Skew: 0.0000°	Inch
New Program 3 of 3 Mill Arc						
001	SET TOOL	From		Tool		
002	MILL LINE	X1	3.7190 Abs	0.5000 Inch		
003	MILL ARC	Y1	-1.4920 Abs	FL END ML Type		
		To		Offset Right		
		X2	× Abs	Feed 10.0 IPM		
		Y2	× Abs	Center		
		Z		X	Abs	
		Begin	0.0100 Abs	Y	Abs	
		End	-0.2000 Abs	3rd Point		
		Feed	10.0 IPM	X3	Abs	
		Radius		Y3	Abs	
		Direction		Sweep Angle		
		CCW				
The TO point must be specified.						
Trig	Geometry	RPM				



- Define a tool by pressing the TOOL key and program a half inch diameter.




- Press USE.


- Next press the LINE button. Program a line from the tangent point of the 1.492 radius to the tangent point of the 0.523 radius. Program the Z Begin at 0.01" and the Z End at -0.2" and a right offset.



- Begin an arc. The From point is carried forward from the line. The to point is not known. With the highlight in the To point, press the Calculator Key then the Geometry soft key.




From	To
X = 0.0000	X = 3.7190
Y = -1.4920	Y = -1.4920







- 7 Clear Calculator
- 8 Save Calculator
- 9 Load Calculator
- 1 Load Program
- Calc





- ▶ Once in the Geometry calculator press the Calc Functions soft key and arrow down to Load Program and press Enter or press the 4 Key to bring the Line created in our program into the calculator.
- ▶ In the geometry calculator, the order of the geometry in the list is not important. We will begin constructing the geometry we can define.
- ▶ Press the Arc key and create an arc describing the inside bend centered on X,Y zero. Press USE.
- ▶ Create a second arc describing the right end. You can see that the Y center from zero is 0.523 inches above the -1.490 inch tangent point.
 $0.523 - 1.490 = -0.969$
- ▶ The radius is 0.523. Select CCW and press USE.

Center **Radius**
X = 3.7190 **R = 0.5230**
Y = -0.9690 **Dir = CCW**





Select Feature

- ▶ Select each of the two arcs you created by highlighting them and pressing the Select Feature soft key.



Find Arc



- ▶ Press the Find Arc soft key and enter a radius of 3.240. All possible variations of this arc will appear.



Keep One Result



Clear Results


- ▶ Highlight the desired arc and press the Keep One Result soft key, followed by the Clear Results soft key. The kept arc is now part of your geometry list and the remaining found arcs are discarded.







- ▶ Create a Point describing the left end of the top line as shown on the print.
- ▶ Press the POS key and enter Position X = 3.0210, Y = 3.4710.
- ▶ Press USE.
- ▶ Change the left arc to a radius of 1.492.
- ▶ Highlight the arc (step 2) and press ENTER.
- ▶ Change the radius to 1.492 and press USE.







- ▶ Select the point (step 5) and the 1.492 arc (step 2) then FIND LINE. Keep the desired line.
- ▶ Select only the newly found line then FIND LINE. Enter a distance of 0.827. ($1.492r - 0.665r = 0.8270$) Keep the desired line.
- ▶ Select the new found line and the 3.240 radius (step 4) and FIND ARC with a radius of .665 Keep the desired arc. Clear the remaining results.
- ▶ Create a vertical line from the top right of the part. From $X1 = 3.431$, $Y1 = 3.471$, To $X2 = 3.431$ $Y = 2.000$. The length is not critical. You only need to insure it is well placed in X.



Keep One
Result

Return
Feature

- ▶ Select this line and the line tangent to the 0.665 radius (step 7) then press Find Point. Highlight and keep the found point.
- ▶ Select the 0.523 arc (step 3) and the 3.240 arc (step 4) and press find point. Remember, this is where we left off in our program when we entered the geometry calculator.
- ▶ Highlight this point (step 11) and press Keep One Result, then press Return Feature.





CALC

Geometry

Return
Feature

- ▶ The coordinates of the found point are returned to the waiting Mill Arc step.
- ▶ Enter the 0.523 radius.
- ▶ Insure the direction is CCW.
- ▶ Press USE.
- ▶ Return to the Geometry Calculator by pressing the CALC button then the Geometry soft key.
- ▶ Highlight the 3.240" radius Geoarc (step 4) and press the Return Feature soft key.
- ▶ Press USE.
- ▶ Highlight the 0.665" radius Geoarc (step 8) and press the Return Feature soft key.
- ▶ This arc has been returned with a CCW direction and the end points reversed. We can easily fix this.

From		
X1	<input type="text" value="3.7190"/>	Abs
Y1	<input type="text" value="-1.4920"/>	Abs
To		
X2	<input type="text" value="4.0107"/>	Abs
Y2	<input type="text" value="-0.5349"/>	Abs
Z		
Begin	<input type="text" value="0.0100"/>	Abs
End	<input type="text" value="-0.2000"/>	Abs
Feed	<input type="text" value="10.0"/>	IPM
Radius		
	<input type="text" value="0.5230"/>	Minor
Direction		
	<input type="text" value="CCW"/>	



```

New Program
001 SET TOOL
002 MILL LINE
003 MILL ARC
004 MILL ARC
005 MILL ARC
    
```


Step Functions

Reverse Step


- ▶ Highlight the Offset field and choose Inside.
- ▶ Press USE.
- ▶ Now Highlight the MILL ARC, step (Step 5), and press the Step Functions soft key then press the Reverse Step soft key. The Reverse Step functions flips the step without the need for extensive editing.

Mill Arc		
From		
X1	-0.3330	Abs
Y1	0.5756	Abs
To		
X2	0.3752	Abs
Y2	-0.5490	Abs
Z		
Begin	0.0100	Abs
End	-0.2000	Abs
Feed	10.0	IPM
Radius		Minor
Direction	CCW	
Tool	0.2500	inch
		Type
Offset	Right	
Feed	10.0	IPM

Before Reverse Step



After Reverse Step



With the continuous tool path maintained by reversing the arc in program step 5 we can continue building our path.

CALC

Geometry



Return
Feature

Reverse
Step

- ▶ Insure your curser is under the last step of the program and press the CALC key then the Geometry soft key to return to the geometry calculator.
- ▶ Highlight the GEOLINE (Step 7) and press the Return Feature soft key.
- ▶ This step also needs to be reversed. Before doing so highlight the offset and switch it to Left. This is needed because the reverse step function automatically reverses the offset to maintain a continuous tool path. When reversed, the offset will become Right once again.
- ▶ Press USE then highlight the MILL LINE step and press the Step Functions soft key then press the Reverse Step soft key.

Step	Description
001	SET TOOL
002	MILL LINE
003	MILL ARC
004	MILL ARC
005	MILL ARC
006	MILL LINE


An open bracket between the step number and description indicates the tool path is continuous and open ended.





We can continue building our path. Because we know the end point for the next two step we will program the lines without returning to the calculator.



- ▶ Press the LINE key.
- ▶ The from point, offset, Z information and speeds are carried forward.
- ▶ Enter the end point of $X2 = 3.431''$, $Y2 = 3.471''$.



- ▶ Press USE.
- ▶ Press the LINE key.
- ▶ The from point, offset, Z information and speeds are carried forward.
- ▶ Enter the end point of $X2 = 3.021''$, $Y2 = 3.471''$.
- ▶ Press USE.



For the next step, return to the geometry calculator and return the line, step 6.

CALC

Geometry

Return Feature

ARC

CALC



Geometry

Select Feature

Find Point

Keep One Feature


- ▶ Insure your curser is under the last step of the program and press the CALC key then the Geometry soft key to return to the geometry calculator.
- ▶ Highlight the GEOLINE (Step 6) and press the Return Feature soft key.
- ▶ Press USE.
- ▶ Finally while still in the program editor, press the ARC key to create an arc. The end point is what we require.
- ▶ Press the CALC key then the Geometry soft key to return to the geometry calculator.
- ▶ Highlight steps 1 and 2 and press the Select Feature soft key to select both.
- ▶ Press the Find Point soft key.
- ▶ Highlight the found point and press the Keep One Feature soft key
- ▶ Press the return Feature soft key.
- ▶ Arrow down to the radius and enter 1.492”
- ▶ Arrow to the Direction and choose CCW
- ▶ Press USE.




Geometry Calculator Example Program

With the use of the geometry calculator we were able to use the information provided on the left and determine the rest of the dimensions as shown on the right.

Information Provided




Results



Geo Exercise 1

Finding unknown tangents

- ▶ Program the appropriate tool for the job.
- ▶ Program a line from zero to 2 inches.
- ▶ Begin another line. With the curser in the TO field, press the CALC key then the Geometry soft key.
- ▶ In the Geometry calculator, program a line from X, Y zero to Y 2 at 70°.
- ▶ Program a second line from X 2, Y 0 zero to Y 2 at 110°.
- ▶ Using the arrow keys and the Select Feature soft key, highlight and select both lines then press the Find Arc soft key. Enter a radius of .625".
- ▶ Choose the desired arc from the list of found arcs and press the Keep One soft key.
- ▶ Using the arrow keys and the Select Feature soft key, highlight and select the new arc only. Press the Find Point soft key. Press the Keep All Results soft key.
- ▶ Highlight the point representing the right tangent point of the arc and press the Return Feature soft key. The point is now transferred into your program step. Press USE.
- ▶ Program an arc. With the curser in the TO field, press the CALC key then the Geometry soft key.
- ▶ Highlight the point representing the left tangent point of the arc and press the Return Feature soft key. The point is now transferred into your program step. Enter a radius of .625 and insure the direction is CCW. Press USE.
- ▶ Program a line back to X, Y zero.



CALC

Geometry

Select
FeatureFind
ArcSelect
Feature

Geo Exercise 2


Creating a 1" Hexagon

CALC

Geometry

Return
Feature

- ▶ Program the appropriate tool for the job.
- ▶ Press CALC then GEOMETRY to enter the geometry calculator.
- ▶ Create a 1" diameter ARC in the calculator.
- ▶ Select the arc, find line at 30°, and keep the bottom line.
- ▶ Find line at 90° and keep the right and center line.
- ▶ Select the 30° and the center 90° lines, find point, and keep it.
- ▶ Select the left edge 90° and the 30° lines, find point, and keep it.
- ▶ Select the two points, find line, and keep it.
- ▶ Highlight the found line, and press RETURN FEATURE.
- ▶ Rotate the line around zero at 60° repeating five times.
- ▶ Explode the rotate.




Notes


Geo Exercise 3

In the Calculator...

- ▶ Draw an arc with a 45° sweep angle
- ▶ Find the endpoints and center point of the arc.
- ▶ Find the line between center point and end point.
- ▶ Draw a line $.5''$ above zero.
- ▶ Find intersection of the two lines.



TIP: Use polar coordinate
 $R = .75$ $A = -138^\circ$
 to program this point.




In the Calculator

1. Draw an arc with a 45° sweep angle
2. Find the endpoints and center point of the arc.
3. Find the line between center point and end point.
4. Draw a line $.5''$ above zero.
5. Find intersection of the two lines.


Geo Exercise 4

Create the outer profile and the center relief cut



Geo Exercise 5


You're handed a sketch and asked to cut this out of $\frac{1}{2}$ " aluminum



Exercise 1

Notes (unless otherwise specified)


- ▶ All dimensions are in inches.
- ▶ All radii are 0.25.



Exercise 2

Notes (unless otherwise specified)


- ▶ All dimensions are in inches.
- ▶ All radii are 0.25.



Exercise 3

Notes (unless otherwise specified)


- ▶ All dimensions are in millimeters.



Exercise 4

Notes (unless otherwise specified)


- ▶ All dimensions are in inches.
- ▶ Tool radius allowed on inside corners.




Exercise 5

Notes (unless otherwise specified)


- ▶ All dimensions are in inches.



Exercise 6






Exercise 7



Exercise 8


Micrometer Box

EXERCISES



Exercise 9

Dial Indicator Storage




EXERCISES

Exercise 10

DXF Import

- ▶ File EXERCISE 8.DXF provided



Exercise 11

G-Code Editing

- ▶ NC file provided


EXERCISES

Stop Time: 4:36:08 Tool: 0.5000 Inch Datum: 1 Scale: 1.0000 Skew: 0.0000° Inch

WHL-FIN 516.NC.NC 1 of 53062

```

00001 %
00002 O0000
00003 (PROGRAM NAME - WHL-FIN
00004 (DATE=DD-MM-YY - 30-08-01
00005 G20
00006 G0G17G40G49G80G90
00007 G120 X3 Y3 Z0 I-3 J-3 K-1
00008 (5/16 BALL ENDMILL TOOL -
00009 T1M6
00010 G0G90X-.068Y-2.7544S2139M
00011 G43H1Z.1
00012 Z.05
00013 G1Z-.7032F20.
00014 X.068F40.
00015 G0Z.05
00016 Z.1
00017 X.1491Y-2.7514
00018 Z.05
00019 G1Z-.7032F20.
00020 X-.1491F40.
00021 G0Z.05
  
```



Program Functions | Clear Program | Shutdown | Save/ Discard | Run Options

Review

- ▶ Startup
- ▶ Digital Readout Usage
- ▶ Jogging and Positioning
- ▶ Tool Library
- ▶ Canned Cycle Operations
- ▶ Programming
- ▶ Geometry Calculator



ACU-RITE[®]

Made in the USA 

www.acu-rite.com

A member of the HEIDENHAIN family of brands